



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 69429

### CUSTOMER WORK ORDER

WO #: 69429

Customer: 52068 - RODGERS, PHILIP  
A. - 812-202-2565

Tag:

Author: BH

Location: 1230 CHECK BHS EMAIL

Stock #: 11038

Stock Desc: 2022 5W FOREST RIVER  
SABRE 36BHQ

Chassis #: 5ZT3SR1B3N6109325

Serial #: 5ZT3SR1B3N6109325

Mileage:

Licence:

Invoice #:

Date In: 28 NOV 22

Promised:

Date Sched:

Completed: 21 DEC 22

Warr. Date: 22 JAN 22

#### Job #1 - Warranty

COMPLAINT: FIND OUT WHY FRIDGE IS NOT COOLING

CORRECTION: FOUNDS THE REFER WAS 6 DEGREES IN THE BOTTOM AND 54 IN THE TOP I TOOK COVER OFF THE BOTTOM IN FREEZER AND FOUND THE COILS WAS FROZE OVER AND THAT THE PLUG IN THE FREEZER AREA WAS MELTED AND THERE WAS A MELTED SPOT IN THE BACK WALL. I LET THE COILS THAW SOME AND PLUGGED THE FAN FOR THE TOP BACK IN AND IT RAN I SUGGEST A NEW REFER BCD-455WTE-B-04H .

took drawer out of freezer to get to screws in bottom of feet of ref had to take bottom trim off of room to pull ref, pulled ref to get to 12 volt wires, unhooked wires to ref, pulled out, had to take out kitchen table screws and move it out of the way with 4 chairs, had to pull valance down over sun shade, then took out window hard to get out was sealed real good, cleaned around out side where window was sealed, lifted ref out through window, lifted new ref through window, set in place and hooked up 12 volt wires to ref, pushed ref in place and but brackets back in place on feet, took out staples in trim, installed trim on slide out, installed window back in place and sealed on outside, installed valance back in place, installed table back in place with chairs, installed straps back in place on ref, had to put new double sided tape on all 6 pieces. took off all tape in ref and on outside, cleaned window.

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	295.50
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	240.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	364.50

#### Other Services

Code	Description	Qty	Price	Total
EDF	ENVIROMENTAL DISPOSAL FEES	1.00	100.00	100.00

**Subtotal for Job #1: 1,000.00**

#### Job #2 - Warranty

THE COMPARTMENT LATCH ON THE OFF DOOR SIDE IS LOOSE NEEDS TO BE ADJED TO CLOSE SO IT DOES NOT LEAK

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	30.00

**Subtotal for Job #2: 30.00**



Customer #: 52068



Parts Total: 0.00  
Labour Total: 930.00  
Sublet Total: 0.00  
Extras Total: 100.00  
**WORK ORDER TOTAL: 1,030.00**

W/O: 69429

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 21 Dec 2022

Customer Work Order



Customer #:  
52068

