

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1376077
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4FCKZ25PX161022
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$150.00	SITE/WAREHOUSE	017 / 017A
OWNER INFORMATION		ITEM #	ACKF235MBBL
		DEALER RO #	69593
		CLAIM START DATE	01/05/2023
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 20-69-02-17-000708	Operational Description Compartment Door Lock or Slam Latch - Exterior/Compartment Doors/ Adjust/Latch			
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2023-01-05 08:37:23 :: FRONT COMPARTMENT DOOR LOCK INSTALLED WRONG FRONT COMPARTMENT DOOR LOCK WAS NOT INSTALLED RIGHT REINSTALLED LATCH THE PROPER WAY				
	Model #	Dlr Sub Hrs	0.10	Sub Labor Amt	\$15.00
	Serial #	Appr Hrs	0.10	Appr Labor Amt	\$15.00

Notes

Labor

Line# 2	Operation Code 60-139-19-00-001562	Operational Description Sink - Plumbing/Kitchen (Galley) Sink/Reseal/No Tread Code			
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2023-01-05 08:38:42 :: KITCHEN SINK NEEDS SEALED KITCHEN SINK WAS NOT SEALED UP SEALED UP KITCHEN SINK				
	Model #	Dlr Sub Hrs	0.10	Sub Labor Amt	\$15.00
	Serial #	Appr Hrs	0.10	Appr Labor Amt	\$15.00

Notes

Labor

Line# 3	Operation Code 60-141-19-00-001596	Operational Description Tub Surround - Plumbing/Shower, Tub Surround/Reseal/No Tread Code			
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2023-01-05 08:39:31 :: SHOWER SURROUND NEEDS SEALED SHOWER SURROUND NEEDED SEALED UP SEALED UP SHOWER SURROUND				
	Model #	Dlr Sub Hrs	0.30	Sub Labor Amt	\$45.00
	Serial #	Appr Hrs	0.30	Appr Labor Amt	\$45.00

Notes

Labor

Line# 4	Operation Code 60-141-19-00-001614	Operational Description Outside Shower Compartment - Plumbing/Shower, Tub Surround/ Reseal/No Tread Code			
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2023-01-05 08:41:01 :: OUTSIDE SHOWER NEEDS SEALED				

SEALED UP OUTSIDE SHOWER SEALED UP OUTSIDE SHOWER

Model #	Dlr Sub Hrs	0.10	Sub Labor Amt	\$15.00
Serial #	Appr Hrs	0.10	Appr Labor Amt	\$15.00

Notes

Submitted			Approved		
	Labor Amt	\$90.00		Labor Amt	\$90.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$90.00		Total	\$90.00

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.