



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69707
Promised Date:
24 JAN 23

CUSTOMER WORK ORDER

WO #: 69707 (Appointment Date: 20 JAN 2023 - Time: 11:00am)

Customer: 16354 - THARP, JOHN A. -
812-686-7167

Tag:

Author: PH

Location: 0123 SEE IF WO CAN BE
CLOSED TODAY

Stock #: 11044

Stock Desc: 2021 TT COACHMEN

CATALINA 323BHDSCLE

Chassis #: 5ZT2CAXB6MX023193

Serial #: 5ZT2CAXB6MX023193

Mileage: 0

Licence:

Invoice #: 386983

Date In: 20 JAN 23

Promised: 31 JAN 23

Date Sched:

Completed: 23 JAN 23

Warr. Date: 15 OCT 21

Job #1 - External

COMPLAINT: SLIDE SEAL ON BACK SLIDE ROOM HAS POPPED OFF. CUSTOMER WOULD LIKE TO HAVE THE FRONT ONE CHECKED AS WELL.

CORRECTION: HAD TO PLUG IN SHORE POWER TO MOVE BOTH SLIDEOUT OUT AND INSPECTED. THE BACK SLIDEOUT HAD COLAPSED BULB D SEALS ON FRONT AND BACK OF SLIDEOUT. GOT WITH MATT ON A NEW BULB D SEAL. ASKED BJ AND PETE TO GET APPROVAL ON SEAL. BJ SAID OK TO CHANGE BULB D SEAL. USED 14 FT OF BULB D SEAL OUT OF 50 FT. REMOVED SCREW AT BOTTOM OF SEAL TO PULL SEAL OFF. PUT NEW SEAL ON TRACK AND CUT TO LENGTH. FINISHED OFF WITH A SCREW AT THE BOTTOM TO HOLD IN PLACE.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Parts

Part #	Description	Qty	Price	Total
20X48346A	SLIDE OUT, BULB "D" SEAL 1.20" X LENGTH SLIP ONTOP/SIDES/BOTTOM-ABOVE - BLACK LARGE "D" SEAL	14.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #3 - External

COMPLAINT: CUSTOMER NEEDS A KEY FOR THE EXTERIOR KITCHEN

CORRECTION: GOT WITH MATT B ABOUT AN OUTSIDE KITCHEN KEY. HE FOUND THAT THE KEY WAS A CF330. TESTED THE KEY IN THE LOCK FOR THE OUTSIDE KITCHEN. KEY LOCKS AND UNLOCKS DOOR. ZIPTIDE THE NEW INSIDE THE FRONT DOOR.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Parts

Part #	Description	Qty	Price	Total
C01275344K	CF330/CK330 SLAM LATCH KEY	1.00	N/C	N/C

Subtotal for Job #3: 0.00



Customer #:
16354



Job #BRAKE - Warranty

COMPLAINT: JOB #22V477 BRAKE AWAY SWITCH WIRING RECALL

CORRECTION: TOOK PICTURES. CUT THE UNDER BELLY TO REMOVE BREAKAWAY WIRE ATTACHED TO CIRCUIT BREAKER. UNSCREWED THE BATTERY SHUT OFF SWITCH FROM BODY TO ATTACH BREAKAWAY WIRE. CRIMPED WIRE TO BUTT CONNECTER AND BOLTED TO THE BATTERY SIDE OF SHUTOFF SWITCH. TAPED UNDER BELLY BACK UP.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	45.00

Subtotal for Job #BRAKE: 45.00

Parts Total: 0.00
Labour Total: 45.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 45.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 23 Jan 2023

W/O: 69707
Promised Date:
31 JAN 23



Customer #:
16354

