



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69709



Customer #:
51030



CUSTOMER WORK ORDER

WO #: 69709 (Appointment Date: 21 JAN 2023 - Time: 07:00am)

Customer: 51030 - RAAF, KOURTNEY
L. - 812-459-2838

Tag:

Author: PH

Location: 0125 CHECK WORK

Stock #: 10799

Stock Desc: (10799) 2022 FOREST
RIVER CHEROKEE GREY WOLF
23DBH

Chassis #: 4X4TCKY25NK079838

Serial #: 4X4TCKY25NK079838

Mileage:

Licence:

Invoice #: 386981

Date In: 21 JAN 23

Promised:

Date Sched:

Completed: 23 JAN 23

Warr. Date: 19 MAR 22

Job #1 - External

COMPLAINT: WATER PUMP IS NOT WORKING. WILL NOT PRIME. THEY HAVE ANTIFREEZE IN THEIR FRESH TANK TRYING TO WINTERIZE. UNIT IS NOT WINTERIZED

CORRECTION: FOUND WATER PUMP, PUT HOSE IN JUG TO SUCK WATER THROUGH, FOUND ALL FAUCETS WERE OPEN, SHUT OFF ALL FAUCETS EXCEPT ONE AND PRIMED UP PUMP, ALL IS GOOD.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - External

COMPLAINT: ENTRY DOOR SCREEN IS STICKING AND NOT OPENING WITH MAIN DOOR

CORRECTION: CHECKED BOTH DOORS TO MAKE SURE, LEVELED CAMPER AND ADJUSTED STEPS, PULLED DOORS OPEN AND THEY WORK FINE, SCREEN COMES WITH DOOR EVERYTIME.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Subtotal for Job #2: 0.00

Job #22V243 - Warranty

COMPLAINT: RECALL 22V243 LP QUICK CONNECT

CORRECTION: TOOK PICTURE OF QUICK DISCONNECT AND IT NEEDS REPLACED, TOOK OFF OLD ONE AND REPLACED WITH NEW ONE, AND MADE SURE IT DONT LEAK.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	45.00

Subtotal for Job #22V243: 45.00





Parts Total:	0.00
Labour Total:	45.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	45.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 23 Jan 2023

Customer #:
51030

