



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69736



CUSTOMER WORK ORDER

WO #: 69736

Customer: 1000 - BASDEN'S
AMERICAN RV -

Tag:

Author: BH

Location: 0210 CHECK WORK

Stock #: 11015

Stock Desc: 2023 TT FOREST RIVER
CHEROKEE 274RK

Chassis #: 4X4TCKC28PX160894

Serial #: 4X4TCKC28PX160894

Mileage: 0

Licence:

Invoice #:

Date In: 26 JAN 23

Promised:

Date Sched:

Completed: 09 FEB 23

Warr. Date:

Job #1 - Warranty

COMPLAINT: OFF DOOR SIDE SLIDE OUTSIDE REAR SEAL COMING OFF AND HANGING

CORRECTION: RIGHT REAR TOP OF SLIDE ROOM IS SUCKING IN BULB SEAL AND WIPER SEAL AND TEARING IT AWAY FROM THE METAL, TOOK BULB SEAL OFF AND PULLED OUT STAPLES AND HAD TO GET GEOSSELL OFF OF METAL AND SEAL, PULLED CHANNEL AND GOT STRAIGHT, GAINED 3/4 OF INCH SO ROOM WOULD NOT HIT IT, RESTAPLED BACK IN PLACE AND SEALED, INSTALLED NEW BULB SEAL, IT WAS TORE UP, TESTED ALL GOOD.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	150.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00

Parts

Part #	Description	Qty	Price	Total
20X48346A	SLIDE OUT, BULB "D" SEAL 1.20" X LENGTH SLIP ONTOP/SIDES/BOTTOM-ABOVE - BLACK LARGE "D" SEAL	7.00	0.87	6.09

Subtotal for Job #1: 156.09

Job #2 - Warranty

COMPLAINT: BATH ROOM DOOR HITS

CORRECTION: TOOK OFF PLASTIC DOOR FRAME WRAP AND CUT DOWN PANELING OVERHANG AND REINSTALLED PLASTIS WRAP AND DOOR CATCH AND ADJUSTED DOOR KNOB PLUNGER.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	30.00

Subtotal for Job #2: 30.00

Job #3 - Warranty

COMPLAINT: CABINETS ABOVE THE FIRE PLACE RUB AND THE GLASS IS CRACKED

CORRECTION: GLASS IS BROKEN IN CABINET DOOR.NEED NEW GLASS.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	60.00

Customer #: 1000



Z990 MISC LABOUR CODE (EXTERNAL) DGH 0.00

Parts

Part #	Description	Qty	Price	Total
30I116421A	11" X 11" REEDED GLASS	1.00	4.53	4.53

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-DOOR GLASS	1.00	15.88	15.88

Subtotal for Job #3: 80.41

Job #4 - Warranty

COMPLAINT: FRIDGE DOOR WILL NOT SHUT

CORRECTION: drilled out holes in latch and put different bolts in and had to raise door hinges to catch latch all is good.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	45.00

Subtotal for Job #4: 45.00

Parts Total: 10.62
Labour Total: 285.00
Sublet Total: 0.00
Extras Total: 15.88
WORK ORDER TOTAL: 311.50

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 09 Feb 2023

Customer Signature : _____

W/O: 69736



Customer #: 1000

