

e-Authorization

2/9/20
05:28:55 1

3-Authorization number PA03360828 Reference no: 69738 Status: Approved Approved by steic Approved date 2/3/2023
 rving Name Address Address VIN Retail sold on

34 Basden's American RV Basden's American RV 4YDTSG129N3111789
 600 E Baseline Rd
 Evansville, IN 47725

Qty	Base hours	Complaint / Cause / Correction
1	0.50	Complaint:BRING UNIT IN AND FIND WHERE ALL THE PAPER IS COMING LOOSE AND MARK IT WITH TAPE Cause:BRING UNIT IN AND TAKE A PIC OF THE PAPER COMING OFF OF THE CABINETS THERE IS 120 FT NEEDS TO BE REPLACED THERE IS 120 FOOT THAT NEEDS TO BE REPAIRED PLEASE ADJUST TIME ACCORDINGLY WILL HAVE TO PEEL OFF OLD SAND IT DOWN CLEAN REPLY NEW PAPER AND MAKE LOOK GOOD
		Correction:WILL HAVE TO PEEL OFF OLD SAND IT DOWN CLEAN REPLY NEW PAPER AND MAKE LOOK GOOD
		KRV - Our laminate stle supplier has released a video showing how the stle repairs can be performed. Please review and if you have any questions please let us know. GENESIS REPAIR VIDEO https://www.youtube.com/watch?v=WGc01fntTzy KRV - VCB

3-Authorization number PA03360828

20.00

For paper claims **only** use one pre-authorization number per warranty claim for multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the