

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 69791
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 10718 - 2022 SPRINGDALE 280BH 4YDTSGN23N3107119
VIN: 4YDTSGN23N3107119 HIN: SER#: 4YDTSGN23N3107119
Mileage: 0 Work Order Comp: 15 FEB 23
Auth. No: Dealer #: 1194
Warr. Date: Work Order Date: 06 FEB 23 Inv #: 387554

WO # Job # Description JOB INFORMATION

69791 2 CABINET STILE VINEAR. PAPER BUBBLED OVER REFER
FOUND SEVERAL SPOTS WEHERE VINER PAPER WAS PEALING AWAY. HAD SOME
AT THE BOTTOM OM OF KITCHEN CABNET NEAR BEDROOM. BOTTOM OF
BATHROOM SINK. INSIDE CABNIET DOOR, FOUND SOME BY BEDROOM NON
DOOR SIDE CABNIET. FOUND WHERE IT WAS PEALING AWAY AT BATHROOM
DOOR. ALSO THERE IS A SMALL DENT ON REFREDIGERTOR WHERE WHEN
OPENS IT HITS CABNIET NO BUFFER. ALSO SLIDE ROOM NEEDS SEALED
FOUND SEVERAL SPOTS WEHERE VINER PAPER WAS PEALING AWAY. HAD SOME
AT THE BOTTOM OM OF KITCHEN CABNET NEAR BEDROOM. BOTTOM OF
BATHROOM SINK. INSIDE CABNIET DOOR, FOUND SOME BY BEDROOM NON
DOOR SIDE CABNIET. FOUND WHERE IT WAS PEALING AWAY AT BATHROOM
DOOR. ALSO THERE IS A SMALL DENT ON REFREDIGERTOR WHERE WHEN
OPENS IT HITS CABNIET NO BUFFER. ALSO SLIDE ROOM NEEDS SEALED
REMOVE TAPE AND SAND DOWN. ON BATHROOM SINK AREA. PUT ON NEW
TAPE. PULL FREIGE OUT AND REMOVE TAPE ABOVE FREIGE AND SAND DOWN.
PUT ON NEW TAPE. PUT FREIGE BACK. REMOVE 4 DRAWERS AND PEAL TAPE
OFF AND SAND. PUT ON NEW TAPE. PUT DRAWERS BACK. STAPLE SIDE
PANEL. REMOVE TAPE IN BEDROOM ON 2 CABINETS. SAND DOWN. PUT ON
NEW TAPE.

69791 3 BATHROOM DOOR HAS SCRATCHES IN IT
BATHROOM DOOR HAS TEARS NEAR HANDLE. DENNY LOOKED AT IT. NEED
APPROVAL FOR NEW BATHROOM DOOR 72/38 IN HEIGHT WIDTH 2FT
BATHROOM DOOR HAS TEARS NEAR HANDLE. DENNY LOOKED AT IT. NEED
APPROVAL FOR NEW BATHROOM DOOR 72/38 IN HEIGHT WIDTH 2FT REMOVED
DOOR AND TOOK HINGES OFF AND PUT THEM ON THE NEW DOOR. SAME WITH

Claim : 69791

WO #	Job #	Description	JOB INFORMATION
------	-------	-------------	-----------------

DOOR KNOB

69791	1	BARREL THAT HOLDS STRING ON BLIND IN UPPER BUNK IS PULLED OUT OF PANELING BARREL THAT HOLDS STRING ON BLINDS CAME LOSE ON UBER BUNK. REATTACHED A LITTLE LOWE AND FILLED IN THE OLD HOLE BARREL THAT HOLDS STRING ON BLINDS CAME LOSE ON UBER BUNK. REATTACHED A LITTLE LOWE AND FILLED IN THE OLD HOLE
-------	---	---

69791	4	SLIDEROOM SEALS NEED SILICONED SLIDEROOM SEALE NEEDED SEALED UP. SEALED UP SLIDE ROOM SLIDEROOM SEALE NEEDED SEALED UP. SEALED UP SLIDE ROOM
-------	---	--

Part No	Job#	Description	PARTS	Qty	Price	Total
704717	2	8" SEAM TAPE UNI MAT GREY		22.00	1.17	25.74
682825	3	Passage - Door - 1 3/8" x 24" x 7		1.00	83.40	83.40

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	2	MISCELLANEOUS REPAIR		1.00	150.00	150.00
Z990	2	MISCELLANEOUS REPAIR		1.00	150.00	150.00
Z990	2	MISCELLANEOUS REPAIR		0.00	150.00	0.00
Z990	2	MISCELLANEOUS REPAIR		4.00	150.00	600.00
Z990	2	MISCELLANEOUS REPAIR		4.00	150.00	600.00
Z990	3	MISCELLANEOUS REPAIR		0.00	150.00	0.00
Z990	3	MISCELLANEOUS REPAIR		0.00	150.00	0.00
Z990	3	MISCELLANEOUS REPAIR		0.20	150.00	30.00
Z990	1	MISCELLANEOUS REPAIR		0.10	150.00	15.00
Z990	4	MISCELLANEOUS REPAIR		0.20	150.00	30.00

Excode	Job#	Description	EXTRAS	Qty	Price	Total
FRT	2	UPS-SEAM TAPE		1.00	15.99	15.99
FRT	3	UPS FREIGHT - DOOR		1.00	141.01	141.01

Parts Total:	109.14
Labour Total:	1,575.00
Sublet Total:	0.00
Extras Total:	157.00

>>>> Claim Total: 1,841.14

Customer Signature: _____

Date: _____