



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69791
Promised Date:
28 FEB 23



CUSTOMER WORK ORDER

WO #: 69791

Customer: 1000 - BASDENS
AMERICAN RV -

Tag:

Author: BH

Location: 0216 CHECK STATUS WITH
BB

Stock #: 10718

Stock Desc: 2022 TT KEYSTONE

SPRINGDALE 280BH

Chassis #: 4YDTSGN23N3107119

Serial #: 4YDTSGN23N3107119

Mileage: 0

Licence:

Invoice #:

Date In: 06 FEB 23

Promised: 28 FEB 23

Date Sched:

Completed: 15 FEB 23

Warr. Date:

Job #1 - Warranty

COMPLAINT: BARREL THAT HOLDS STRING ON BLIND IN
UPPER BUNK IS PULLED OUT OF PANELING

CAUSE: BARREL THAT HOLDS STRING ON BLINDS CAME LOSE ON UPPER BUNK. REATTACHED A
LITTLE LOWE AND FILLED IN THE OLD HOLE

CORRECTION: BARREL THAT HOLDS STRING ON BLINDS CAME LOSE ON UPPER BUNK.
REATTACHED A LITTLE LOWE AND FILLED IN THE OLD HOLE

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	15.00
Subtotal for Job #1:			15.00

Job #2 - Warranty

COMPLAINT: CABINET STILE VENEER. PAPER BUBBLED
OVER REFER

CAUSE: FOUND SEVERAL SPOTS WHERE VENEER PAPER WAS PEELING AWAY. HAD SOME AT THE
BOTTOM OF KITCHEN CABINET NEAR BEDROOM. BOTTOM OF BATHROOM SINK. INSIDE
CABINET DOOR, FOUND SOME BY BEDROOM DOOR SIDE CABINET. FOUND WHERE IT WAS
PEELING AWAY AT BATHROOM DOOR. ALSO THERE IS A SMALL DENT ON REFRIGERATOR
WHERE WHEN OPENS IT HITS CABINET NO BUFFER. ALSO SLIDE ROOM NEEDS SEALED

CORRECTION: FOUND SEVERAL SPOTS WHERE VENEER PAPER WAS PEELING AWAY. HAD SOME
AT THE BOTTOM OF KITCHEN CABINET NEAR BEDROOM. BOTTOM OF BATHROOM SINK.
INSIDE CABINET DOOR, FOUND SOME BY BEDROOM DOOR SIDE CABINET. FOUND WHERE
IT WAS PEELING AWAY AT BATHROOM DOOR. ALSO THERE IS A SMALL DENT ON
REFRIGERATOR WHERE WHEN OPENS IT HITS CABINET NO BUFFER. ALSO SLIDE ROOM
NEEDS SEALED

REMOVE TAPE AND SAND DOWN. ON BATHROOM SINK AREA. PUT ON NEW TAPE. PULL FREIGE
OUT AND REMOVE TAPE ABOVE FREIGE AND SAND DOWN. PUT ON NEW TAPE. PUT FREIGE
BACK. REMOVE 4 DRAWERS AND PEEL TAPE OFF AND SAND. PUT ON NEW TAPE. PUT DRAWERS
BACK. STAPLE SIDE PANEL. REMOVE TAPE IN BEDROOM ON 2 CABINETS. SAND DOWN. PUT ON
NEW TAPE.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	150.00
Z990	MISCELLANEOUS REPAIR	RAB	150.00
Z990	MISCELLANEOUS REPAIR	BB	0.00



Customer #:
1000



W/O: 69791
Promised Date:
28 FEB 23



Customer #:
1000



Z990	MISCELLANEOUS REPAIR	BB	600.00
Z990	MISCELLANEOUS REPAIR	BB	600.00

Parts

Part #	Description	Qty	Price	Total
704717	8" SEAM TAPE UNI MAT GREY	22.00	1.17	25.74

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-SEAM TAPE	1.00	15.99	15.99

Subtotal for Job #2: 1,541.73

Job #3 - Warranty

COMPLAINT: BATHROOM DOOR HAS SCRATCHES IN IT

CAUSE: BATHROOM DOOR HAS TEARS NEAR HANDLE. DENNY LOOKED AT IT. NEED APPROVAL FOR NEW BATHROOM DOOR 72/38 IN HEIGHT WIDTH 2FT

CORRECTION: BATHROOM DOOR HAS TEARS NEAR HANDLE. DENNY LOOKED AT IT. NEED APPROVAL FOR NEW BATHROOM DOOR 72/38 IN HEIGHT WIDTH 2FT
REMOVED DOOR AND TOOK HINGES OFF AND PUT THEM ON THE NEW DOOR. SAME WITH DOOR KNOB

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	0.00
Z990	MISCELLANEOUS REPAIR	BB	0.00
Z990	MISCELLANEOUS REPAIR	BB	30.00

Parts

Part #	Description	Qty	Price	Total
7733	Passage - Door - 1 3/8" x 24" x 72 1/2" - Carb 2 - L&L - Guan Tree Natural	1.00	83.40	83.40

Other Services

Code	Description	Qty	Price	Total
FRT	UPS FREIGHT - DOOR	1.00	141.01	141.01

Subtotal for Job #3: 254.41

Job #4 - Warranty

COMPLAINT: SLIDEROOM SEALS NEED SILICONED

CAUSE: SLIDEROOM SEALE NEEDED SEALED UP. SEALED UP SLIDE ROOM

CORRECTION: SLIDEROOM SEALE NEEDED SEALED UP. SEALED UP SLIDE ROOM

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	30.00

Subtotal for Job #4: 30.00

Parts Total:	109.14
Labour Total:	1,575.00
Sublet Total:	0.00
Extras Total:	157.00
WORK ORDER TOTAL:	1,841.14



Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 15 Feb 2023

W/O: 69791
Promised Date:
28 FEB 23



Customer #:
1000

