

e-Authorization

4/3/20
11:31:25

3- Authorization number PA03364657 Reference no: 69808 Status: Approved Approved by RogerB Approved date 3/7/2023

Customer Name Address VIN Retail sold on

Job #	Customer	Address	Job Date					
34	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	4YDT33126M5353774 8/19/2021					
Job Root of operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1 7102943L	Pre-Delivery Insp	0.00	2.00	2.00		1	2.00	Complaint:BRING UNIT IN AND WASH AND DO A WALK THUR WITH CUSTOMER
2 3500208A	Vinyl Flooring - R	300.00		0.60		1	0.60	KRV - sent to BR 3/2/23 RA Cause:WASHED DIRTY CAMPER AND DID WALK THUR Correction:CLEANED CAMPER AND DID WALK THUR Complaint:SPOT ON THE FLOOR IS DAMAGED NEED TO REPAIR IT FROM THE LIVING ROOM TO BUNK ROOM Cause:HAVE FIBER NEW COME AND FIX THE FLOOR Correction:HAVE FIBER NEW COME AND FIX FLOOR
3 3303808B	Sofa - Jack Knife	0.00		0.50		1	0.50	Complaint:THE COUCH HAS A SPOT IN IT DAMAGED FROM WHEN THE UNIT WAS AT THE FACTORY Cause:FOUND COUCH DAMAGED Correction:REPLACE COUCH
4 3201814B	Decorative Wood	0.00	0.20	0.20		1	0.20	Complaint:IN THE BUNK ROOM THE WALL PAPER IS COMING OFF AND LOOKS LIKE THEY OVER LAID PAPER AND DOES NOT LOOK GOOD Cause:NEED SEAM TAPE TO COVER A BAD SPOT ON THE WALL FROM FACTORY REPAIR Correction:REPAIR BAD SPOT ON THE WALL FROM FACTORY REPAIR
5 3201809B	Decorative Wood	0.00	0.20	0.20		1	0.20	Complaint:TOP TRIM ON THE LIVING ROOM SLIDE IS DAMAGED Cause:TRIM ON THE SLIDE ROOM IS DAMAGED Correction:NEED TO PULL OFF TRIM AND REPLACE WITH NEW
Authorization number PA03364657								
				3.50				

Customer paper claims only use one pre-authorization number per warranty claim for multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the