



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69879
Promised Date:
28 FEB 23

CUSTOMER WORK ORDER

WO #: 69879

Customer: 1000 - BASDEN'S
AMERICAN RV -

Tag:

Author: BH

Location: 0223 CHEC STATUS WITH
ZS

Stock #: 10963

Stock Desc: 2023 5W KEYSTONE
COUGAR HALF-TON 27SGS

Chassis #: 4YDFCGM25PV500817

Serial #: 4YDFCGM25PV500817

Mileage:

Licence:

Invoice #:

Date In: 20 FEB 23

Promised: 28 FEB 23

Date Sched:

Completed: 22 FEB 23

Warr. Date: 25 FEB 23

Job #1 - Warranty

COMPLAINT: RIGHT REAR JACK HAS ERROR. WILL NOT
CLEAR.

CAUSE: RIGHT REAR JACK HAS ERROR. WILL NOT CLEAR.

CORRECTION: Right rear jack will not operate. Control panel showing an error. Tried to reset jacks, but still has error. Checked all wiring. Jack has power being sent to it, but still does not operate. Removed jack motor and installed a test motor. Jack will now operate as it should. Jack motor needs replaced.
2/20/2023: Turned in parts request for a new jack motor.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	120.00
Z990	MISCELLANEOUS REPAIR	DKM	0.00
Z990	MISCELLANEOUS REPAIR	DKM	0.00

Parts

Part #	Description	Qty	Price	Total
458263	Jack - Motor - Hall Effect - 343758 - LCI	1.00	278.08	278.08

Other Services

Code	Description	Qty	Price	Total
FRT	UPS- MOTOR	1.00	18.70	18.70

Subtotal for Job #1: 416.78

Parts Total: 278.08
Labour Total: 120.00
Sublet Total: 0.00
Extras Total: 18.70
WORK ORDER TOTAL: 416.78

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 22 Feb 2023



Customer #:
1000