

BASDEN RV CENTER, INC D.B.A. AMERICAN RV  
600 E. Baseline Rd.  
Evansville, IN  
US  
47725  
812-867-5200

WARRANTY CLAIM # 69895  
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER  
Customer: 1000 - BASDEN'S AMERICAN RV  
Address: 600 E. BASELINE RD. EVANSVILLE, IN  
USA  
47725

Phone:

Stock Number: 10630 - 2023 CATALINA 343BH7SLE 5ZT2CAZB4PX028622  
VIN: 5ZT2CAZB4PX028622 HIN: SER#: 5ZT2CAZB4PX028622  
Mileage: 0 Work Order Comp: 28 FEB 23  
Auth. No: Dealer #:  
Warr. Date: Work Order Date: 21 FEB 23 Inv #: 387929

\*\*\*\*\*

WO #	Job #	Description	JOB INFORMATION
69895	1	TEST TV WONT PICK UP CHANNELS TEST TV WON'T PICK UP CHANNELS. Checked all cables for correct location on back of booster. Checked to see if all cables are good. Cable on roof TV antenna had insulator over center coax preventing it from making contact with antenna terminal. Ran channel scan again and TV picked up channels. Outside coax locations were labeled wrong. Added label to cable location on roadside. Changed label on curbside to read only Sattelite instead of Cable/Sattellite. Remounted booster beck in wall.	
69895	2	ENTRY AND SCREEN DOOR NEED ADJUSTED. NOTED ON DELIVERY ENTRY DOOR AND SCREEN DOOR NEED ADJUSTED. NOTED ON DELIVERY. Screen door is hard to close and latch. Entry door has to be slamed to latch closed, then it is hard to open. Adjusted hinges on screen door to allow it to close and stay closed. Adjusted entry door latch. Ground door frame behind latch plate to allow more adjustment. Entry door now easier to close and latch.	
69895	3	TRIM LOOSE ON INSIDE OF ENTRY DOOR. NOTED ON DELIVERY TRIM LOOSE ON INSIDE OF ENTRY DOOR. NOTED ON DELIVERY. Trim next to entry door on the inside is loose and not secured to wall. Reattached trim with brad nails. Filled all holes with matching putty.	

\*\*\*\*\*

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.76	160.00	121.60

Claim : 69895

\*\*\*\*\*  
Lab Code Job# Description LABOUR Hrs Rate Total  
\*\*\*\*\*  
Z990 1 MISC LABOUR CODE (EXTERNAL) 0.26 160.00 41.60  
Z990 1 MISC LABOUR CODE (EXTERNAL) 0.08 160.00 12.80  
Z990 2 MISC LABOUR CODE (EXTERNAL) 0.30 160.00 48.00  
Z990 3 MISC LABOUR CODE (EXTERNAL) 0.20 160.00 32.00

Parts Total: 0.00  
Labour Total: 256.00  
Sublet Total: 0.00  
Extras Total: 0.00

>>>> Claim Total: 256.00

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_