



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69898
Promised Date:
22 FEB 23



CUSTOMER WORK ORDER

WO #: 69898

Customer: 53399 - WALLACE,
AMANDA - 812-304-9063

Tag:

Author: BH

Location: 0310 BH TO CHECK STATUS

Stock #: 10740

Stock Desc: 2022 TT COACHMEN
FREEDOM EXPRESS 320BHDSLE

Chassis #: 5ZT2FEXB5NW023319

Serial #: 5ZT2FEXB5NW023319

Mileage: 0

Licence:

Invoice #:

Date In: 22 FEB 23

Promised: 25 FEB 23

Date Sched:

Completed: 10 MAR 23

Warr. Date: 22 FEB 23

Job #FPDINTT - Internal

COMPLAINT: Transferred to BAS*69956 on 27 FEB 23

Estimate amount was 0.00

FINAL PDI ON NEW TRAVEL TRAILERS

CORRECTION: found unit in showroom set up, close up and get help to get out of showroom, LP leak will not hold for drop test, have job added, water leaking from underbelly have job added, trim on slideroom loose renail, bedroom cabinet door loose, adjust and tighten up, strap for bathroom door broken replace with new strap from parts,

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JP	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JP	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JP	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JP	N/C

Subtotal for Job #FPDINTT: 0.00

Job #WALK - Internal

Transferred to BAS*69956 on 27 FEB 23

Estimate amount was 180.00

WALK THRU

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C

Subtotal for Job #WALK: 0.00

Job #WINTER - Internal

COMPLAINT: Transferred to BAS*69956 on 27 FEB 23

Estimate amount was 0.00

WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER

WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CORRECTION: blow out lines, reset bypass valves to winter and pump in 3 gallons of antifreeze through

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	JP	N/C



Customer #:
53399



W/O: 69898
 Promised Date:
 25 FEB 23



Customer #:
 53399



Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
Subtotal for Job #WINTER:				0.00

Job #ICSH - Internal

COMPLAINT: Transferred to BAS*69956 on 27 FEB 23
 Estimate amount was 0.00
 INSTALL CUSTOMER SUPPLIED HITCHWORK

CAUSE: INSTALL HITCH

CORRECTION: INSTALLED HITCH AND BRACKETS, ADDED 3 WASHERS TO HITCH HEAD

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Subtotal for Job #ICSH:			0.00

Job #1 - Warranty

COMPLAINT: UNIT WONT HOLD LP PRESSURE

CAUSE: drop test will not hold,
 UNIT ROBBED FROM 5ZT2FEUB1NW024391, THIS UNIT IS NOT ON LOT AFTER GOING THROUGH THE LOT 2 TIMES FOUND OUT UNIT WAS SOLD, RANGE WAS ROBBED FROM 5ZT2FELB6PW027176 TO MAKE DELIVERY, GO OUT ON LOT ANFIN D UNIT BRING IN INSTALL RANGE, RUN DROP TEST ON LP SYSTEM (AS PER NFPA 1192) PUT UNIT BACK ON SALES LOT,

CORRECTION: DROP TEST WILL NOT HOLD, FOUND #1 PIG TAIL ON TANK CONTION BROKEN, REPLACE PIG TAIL, RETEST, DROP TEST WILL NOT HOLD, LP DETECTOR SET OFF BY TANKS, DISCONET LP LINE FROM BOTTOM OF REGULATOR AND RUN DROP TEST ON REGULATOR, PASSED, CHECK WATER HEATER VALVE FOR LEAK, CHECK FURNACE EXSAST FOR LP, REMOVE STOVE TOP AND TEST VALVES, FOUND 1 VALVE IS BLOWING BUBBLES, MAGIC CHEF M# MCFR17TTB, SER RVO0521Y011310, PULL RANG LOOSE FROM CABNET DISCONET AND CONET UP TO RUN DROP TEST ON UNIT WITH OUT RANGE UNIT PASSES, RANGE IS BAD, TURN IN PO UNIT ROBBED FROM 5ZT2FEUB1NW024391, THIS UNIT IS NOT ON LOT AFTER GOING THROUGH THE LOT 2 TIMES FOUND OUT UNIT WAS SOLD, RANGE WAS ROBBED FROM 5ZT2FELB6PW027176 TO MAKE DELIVERY, GO OUT ON LOT ANFIN D UNIT BRING IN INSTALL RANGE, RUN DROP TEST ON LP SYSTEM, HELD 8inwc FOR 4 MINNETS (AS PER NFPA 1192) PUT UNIT BACK ON SALES LOT,

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	160.00

Parts

Part #	Description	Qty	Price	Total
F100131928	RANGE, 17" MAGIC CHEF BUILT IN 2 TONE BLACK WHITE LIGHTS (ORDER QTY 2)	1.00	437.38	437.38

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT-RANGE	1.00	96.69	96.69
Subtotal for Job #1:				694.07



W/O: 69898
Promised Date:
25 FEB 23



Customer #:
53399



Job #2 - Internal

COMPLAINT: Transferred to BAS*69956 on 27 FEB 23
Estimate amount was 0.00
SWAP RANGE

CORRECTION: I SWAPPED THE RANGE OUT OF UNIT VIN# 5ZT2FEUB1NW024391 AND INTO UNIT VIN# 5ZT2FEXB5NW023319

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Subtotal for Job #2:			0.00

Job #3 - Warranty

COMPLAINT: Transferred to BAS*69955 on 27 FEB 23
Estimate amount was 0.00
WATER LEAKING FROM UNDERBELLY

CAUSE: nail shot through water line on build and came out after rusting

CORRECTION: pull down underbelly and found water comming off of top ov black tankby toilet, check in sideand can hear water spraing in wall behind toilet,, found wall at floor line has wetnest on board, remove bathroom door and door frame, remove wall board from wall and found a nail hole in pex pipe comming out of floor in wall going to toilet, to get to fittings have to get too line under sink snd disconet for play after disconeting toilet, have to cut bottom wall plate by hole to get pipe to pu and out of floor to change pipe, cut pex bands and insert new pipe in place, connet up water lines and test for leaks, pull nails and staples from wall panel and trim install wall panel and trim, put bathroom sink cabnet back together, install door trim and door for bathroom, clean up, put pipe with nail hole in parts

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Subtotal for Job #3:			0.00

Parts Total:	437.38
Labour Total:	160.00
Sublet Total:	0.00
Extras Total:	96.69
WORK ORDER TOTAL:	694.07

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 10 Mar 2023

