



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69901
Promised Date:
24 MAR 23

CUSTOMER WORK ORDER

WO #: 69901

Customer: 1000 - BASDEN'S
AMERICAN RV -

Tag:

Author: BH

Location: 0430 CHECK WORK

Stock #: 11213

Stock Desc: 2022 TT RIVERSIDE RV

INTREPID 135I

Chassis #: 59CCC1516NL005493

Serial #: 59CCC1516NL005493

Mileage: 0

Licence:

Invoice #:

Date In: 22 FEB 23

Promised: 31 MAR 23

Date Sched:

Completed: 13 APR 23

Warr. Date: 04 APR 22

Job #1 - Warranty

COMPLAINT: INSTALL NEW ROOF FROM RIVERSIDE AND MAKE SURE NOTHING IS SOFT ON THE ROOF

LOOK AT THE ROOF AND FOUND A LARGE GAP IN THE ROOF REPLACE ROOF

CORRECTION: TOOK LOTS OF PICTURES OF ROOF, TOOK SCREWS OUT OF TOP OF REF AND BOTTOM OF REF, PULLED OUT REF TO LOOK AT CEILING, CEILING AND BACK WALL ARE FINE INSIDE, PUT REF BACK IN PLACE AND INSERTED SCREWS BACK IN TOP AND BOTTOM, ROOF ON RIGHT REAR HAS HOLE IN WOOD, AND ROOF MEMBRANE IS SPLIT AND WOOD EXPOSED TO WEATHER, FOR NOW I JUST SEALED ALL OPENING SPOTS, UNTIL NEW ROOF MATERIAL COMES IN, AND SEALED CORNERS.

REMOVED AIRCON. REMOVED VENTS AND SKYLIGHT. REMOVED GUTTERS AND FRONT AND REAR TRIM. PEEL OFF RUBBER ROOF. GLUE DOWN NEW 1/4" UNDER LAYMENT. GLUE DOWN NEW RUBBER ROOF. PUT BACK GUTTERS AND NEW FRONT AND REAR TRIM. CLEAN OFF PUTTY AND PUT NEW PUTTY ON SKYLIGHT AND VENTS AND ANT. PUT BACK AIRCON. DICOR WHERE NEEDED

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	1,214.40
Z990	MISC LABOUR CODE (EXTERNAL)	BB	54.40
Z990	MISC LABOUR CODE (EXTERNAL)	BB	640.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	651.20
Z990	MISC LABOUR CODE (EXTERNAL)	BB	640.00

Parts

Part #	Description	Qty	Price	Total
220849	CONSTRUCTION ADHESIVE	7.00	3.91	27.37

Subtotal for Job #1: 3,227.37

Parts Total: 27.37
Labour Total: 3,200.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 3,227.37



Customer #:
1000

