

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 69907
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 10845 - 2023 CHEROKEE GREY WOLF 23MKBL 4X4TCKY29PK085838
VIN: 4X4TCKY29PK085838 HIN: SER#: 4X4TCKY29PK085838
Mileage: 0 Work Order Comp: 21 MAR 23
Auth. No: Dealer #:
Warr. Date: Work Order Date: 23 FEB 23 Inv #: 388702

WO # Job # Description JOB INFORMATION

69907 2 ZEBRA SLIDE BLIND NOT WORKING
ZEBRA SLIFDE BLINDS NOT WORKING RIGHT. ON FURTHER UINSPECTION I
FOUND FABRIC WAS TORE AND MAIN METAL BEAM WAS BENT CASUING IT NOT
TO GO UP AND DOWN PROPERLEY. NEEDS NEW ONE INSTALLED
ZEBRA SLIFDE BLINDS NOT WORKING RIGHT. ON FURTHER UINSPECTION I
FOUND FABRIC WAS TORE AND MAIN METAL BEAM WAS BENT CASUING IT NOT
TO GO UP AND DOWN PROPERLEY. NEEDS NEW ONE INSTALLED

69907 1 SEAL UNDER SLIDE COMING OFF
SEAL UNDER SLIDE IS COMING OFF THE SCREWS HOLDING IT FELL OUT.
REMOVED OLD SEALANT WHICJ WAS STUCK ON THERE PRETTY GOODAND SLID
SEAL BACK ON AND INSTALLED TWO NEW BLACK SELFTAPPING SCREWS TO
HOLD IT IN PLACE. ONCE SECURED I RESEALED AROUND THE SEAL
SEAL UNDER SLIDE IS COMING OFF THE SCREWS HOLDING IT FELL OUT.
REMOVED OLD SEALANT WHICJ WAS STUCK ON THERE PRETTY GOODAND SLID
SEAL BACK ON AND INSTALLED TWO NEW BLACK SELFTAPPING SCREWS TO
HOLD IT IN PLACE. ONCE SECURED I RESEALED AROUND THE SEAL

69907 3 ENRITY DOOR RUBS
ENTRY DOOR WAS HIITING STRIKING PLATE CASUING IT TO RUB.
ADJUSTED STRIKING PLATE AND TESTTED DOOR WHICH FIXED THE PROBLEM
ENTRY DOOR WAS HIITING STRIKING PLATE CASUING IT TO RUB.
ADJUSTED STRIKING PLATE AND TESTTED DOOR WHICH FIXED THE PROBLEM

Part No Job# Description PARTS Qty Price Total

F100141513 2 SHADE, 64" X 24" ZEBRA SHADE / 20 1.00 80.78 80.78

Lab Code	Job#	Description	LABOUR		Hrs	Rate	Total	

Z990	2	MISC LABOUR CODE (EXTERNAL)			0.00	160.00	0.00	
Z990	2	MISC LABOUR CODE (EXTERNAL)			0.00	160.00	0.00	
Z990	2	MISC LABOUR CODE (EXTERNAL)			0.00	160.00	0.00	
Z990	2	MISC LABOUR CODE (EXTERNAL)			0.20	160.00	32.00	
Z990	1	MISC LABOUR CODE (EXTERNAL)			0.65	160.00	104.00	
Z990	1	MISC LABOUR CODE (EXTERNAL)			-0.65	160.00	-104.00	
Z990	3	MISC LABOUR CODE (EXTERNAL)			0.30	160.00	48.00	

Parts Total:	80.78
Labour Total:	80.00
Sublet Total:	0.00
Extras Total:	31.51

Customer Signature: _____

Date: _____