



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69931
Promised Date:
03 MAR 23



Customer #:
53419



CUSTOMER WORK ORDER

WO #: 69931

Customer: 53419 - COOK, DAN M. -
618-604-3259

Tag:

Author: BH

Location: 0316 CHECK PREAUTH

Stock #: 10769

Stock Desc: 2022 TT COACHMEN
FREEDOM EXPRESS 29SE

Chassis #: 5ZT2FEUB1NW024391

Serial #: 5ZT2FEUB1NW024391

Mileage: 0

Licence:

Invoice #:

Date In: 24 FEB 23

Promised: 02 MAR 23

Date Sched:

Completed: 14 MAR 23

Warr. Date: 02 MAR 23

Job #2 - Warranty

COMPLAINT: DS REAR COMPARTMENT TRIM LOOSE

CAUSE: DOOR SIDE REAR COMPARTMENT TRIM LOOSE.

CORRECTION: Trim bowed because it is too long. Removed trim and shortened. Reattached trim across bottom of compartment.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	32.00

Subtotal for Job #2: 32.00

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: FPDINTT - FINAL PDI ON NEW TRAVEL TRAILER.

CORRECTION: Moved unit into shop from sales lot. Installed new battery. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 80 psi. Recorded all tire serial numbers. Extended all stab jacks. Checked awning. Checked power cord. Checked all interior lights. Checked converter output. Checked roof. Checked all appliances. Range had been robbed from this unit and none working range set in cabinet. Had to rob another range from a stock unit to install in this unit for delivery. Connected to city water and flushed antifreeze from system. Checked for water leaks. Found kitchen sink water lines loose and leaking. Tightened and stopped leak. Toilet fitting leaking also. Tightened fitting and stopped leak. Checked TV, TV Antenna and Radio. Performed LP drop test and set Lp pressure at 10 1/2 in.wc. Checked all cabinets and drawers. Retracted all stab jacks. Moved unit to wash bay area.

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C
5513	A10-3030DAVP 30A TWISTLOCK - 30M ADAPTER PLUG	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00




Job #ICSH - Internal

COMPLAINT: INSTALL CUSTOMER SUPPLIED HITCHWORK
 **SNAP UP BRACKETS INSTEAD OF \$100
 STORE CREDIT, PER DREW**

CORRECTION: Drilled holes and mounted new Sway plate to frame. Installed new snap up brackets @ 29". Installed customer supplied hitch and bars. Set hitch height at 22". Connected 7-way to tow vehicle.

Labor Code	Description	Mechanic DKM	Total N/C
Z990	MISC LABOUR CODE (EXTERNAL)		

Parts Part #	Description	Qty	Price	Total
17208	17208 2-PK SNAP-UP BRACKETS	1.00	N/C	N/C
14-7309	SWAY CONTROL BALL/PLATE	1.00	N/C	N/C
Subtotal for Job #ICSH:				0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.
 INCLUDES 2 GALLONS OF ANTI-FREEZE
 UNITS WITH WASHING MACHINE OR ICEMAKER
 WILL BE EXTRA
 DE-WINTERIZATION IS NOT INCLUDED
 NUMBER OF GALLONS USED _____

CAUSE: WINTER - WINTERIZE UNIT AND DRAIN ALL HOLDING TANKS.

CORRECTION: By-passed water heater. Connected to air and blew out all water lines and faucets. Added antifreeze to all water lines and faucets. Poured antifreeze in all drain traps. Drained asll holding tanks, including water heater.

Labor Code	Description	Mechanic DKM	Total N/C
Z990	WINTERIZE UNIT		

Parts Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
Subtotal for Job #WINTER:				0.00

Job #WALK - Internal

WALK THRU
 Estimated Amount: 180.00

Labor Code	Description	Mechanic	Total N/C
Z990	MISC LABOUR CODE (EXTERNAL)		
Subtotal for Job #WALK:			0.00

Job #3 - Warranty

COMPLAINT: LP/CO DETECTOR KEEPS ALARMING ALL THE TIME

CAUSE: LP/CO DETECTOR KEEPS ALARMING ALL THE TIME.

CORRECTION: LP/CO alarm keeps beeping all the time. Removed and installed new LP/CO alarm.

Labor


Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	48.00

Parts

Part #	Description	Qty	Price	Total
636092	Alarm - LP/CO - Combo - Detector - 12V - 2 Wire - Surface Mount - Black	1.00	43.46	43.46

Subtotal for Job #3: 91.46

Parts Total:	43.46
Labour Total:	80.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	123.46

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 14 Mar 2023

Customer Signature : _____

W/O: 69931
Promised Date:
02 MAR 23



Customer #:
53419

