



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69955
Promised Date:
28 FEB 23



CUSTOMER WORK ORDER

WO #: 69955

Customer: 53399 - WALLACE,
AMANDA - 812-304-9063

Tag:

Author: BH

Location: 0303 SEE IF BH CAN CLOSE
THIS

Stock #: 10740

Stock Desc: 2022 TT COACHMEN
FREEDOM EXPRESS 320BHDSLE

Chassis #: 5ZT2FEXB5NW023319

Serial #: 5ZT2FEXB5NW023319

Mileage: 0

Licence:

Invoice #:

Date In: 27 FEB 23

Promised: 25 FEB 23

Date Sched:

Completed: 28 FEB 23

Warr. Date: 22 FEB 23

Job #3 - Warranty

COMPLAINT: WATER LEAKING FROM UNDERBELLY

CAUSE: nail shot through water line on build and came out after rusting

CORRECTION: pull down underbelly and found water coming off of top of black tank by toilet, check in side and can hear water spraying in wall behind toilet, found wall at floor line has wet nest on board, remove bathroom door and door frame, remove wall board from wall and found a nail hole in pex pipe coming out of floor in wall going to toilet, to get to fittings have to get too line under sink and disconnect for play after disconnecting toilet, have to cut bottom wall plate by hole to get pipe to pull out of floor to change pipe, cut pex bands and insert new pipe in place, connect up water lines and test for leaks, pull nails and staples from wall panel and trim install wall panel and trim, put bathroom sink cabinet back together, install door trim and door for bathroom, clean up, put pipe with nail hole in parts

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	560.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)		0.00

Subtotal for Job #3: 560.00

Parts Total:	0.00
Labour Total:	560.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	560.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 04 Mar 2023

Customer #:
53399

