

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 69957
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 52650 - DALE L. RANEY
Address: 518 ILLINOIS ST CARMI, IL

62821

Phone: 618-380-3363

Stock Number: 10836 - 2022 CHEROKEE 274RK 4X4TCKC26NX157019
VIN: 4X4TCKC26NX157019 HIN: SER#: 4X4TCKC26NX157019

Mileage: 0

Work Order Comp: 21 MAR 23

Auth. No:

Dealer #:

Warr. Date: 27 MAY 22

Work Order Date: 27 FEB 23

Inv #: 388724

WO # Job # Description JOB INFORMATION

69957 1 THE FRONT AND REAR SEAL ON THE SLIDE IS RIPPING
front and rear slide room are tore and need new ones
front and rear slide room are tore and need new ones BM:
INSTALLED NEW SEALS AND A NEW BULB SEAL HAD TO CUT OFF OLD SEALS
THAT WAS TORN AND TRIMED FOR NEW SEAL TO ATTACH TO WALL THEN
GLUED THE CORNERS AND SEALED THE EDGES I SEEN COULPLE OTHER POTS
THAT NEEDED SEALER SO I SEALED THOSE TOO.

69957 2 REAR BUMPPER IS A MESS THE RACK MESSED UP THE BUMPPER

69957 3 THE BED HINDGE IS BROKEN
the bed hinges were missing screws causing it to pop lose and not
function right. installed new screws and tested function several
time to make sure it worked
the bed hinges were missing screws causing it to pop lose and not
function right. installed new screws and tested function several
time to make sure it worked

69957 4 THE BLACK GREY AND FRESH TANKS ARE NOT READING RIGHT
black and gray tanks are not reading right as the wires had come
loose at board. reattached and ran water. filled tanks to full
and then emptyed and re did. got same results. re winterized took
2 gals
black and gray tanks are not reading right as the wires had come
loose at board. reattached and ran water. filled tanks to full
and then emptyed and re did. got same results. re winterized took

Claim : 69957

 WO # Job # Description JOB INFORMATION

 2 gals

69957 2V243 RECALL 22V243 LP QUICK CONNECT
 WENT DOWN TO CAMPER AND TOOK PICTURE, REMOVED QUICK DISCONNECT AND
 INSTALLED NEW ON ,DID DROP TEST, ALL GOOD, .

 Part No Job# Description PARTS Qty Price Total

 346810 1 Seal - Co-Extruded - Wiper - Sing 14.00 2.93 41.02
 13-1095A 1 SLIDE ON "D" SEAL X FT. 9.00 2.22 19.98

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 160.00 0.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 160.00 0.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 2.00 160.00 320.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.00 160.00 0.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.21 160.00 33.60
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.20 160.00 32.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.00 160.00 0.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.15 160.00 24.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.15 160.00 24.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.15 160.00 24.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.30 160.00 48.00
 Z990 V243 MISC LABOUR CODE (EXTERNAL)

Parts Total: 61.00
 Labour Total: 481.60
 Sublet Total: 0.00
 Extras Total: 0.00

>>>>> Claim Total: 542.60

Customer Signature: _____

Date: _____