



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69957
Promised Date:
28 FEB 23

CUSTOMER WORK ORDER

WO #: 69957 (Appointment Date: 27 FEB 2023 - Time: 01:00pm)

Customer: 52650 - RANEY, DALE L. -
618-380-3363

Tag:

Author: BH

Location: 0321 BH CAN THIS BE
CLOSED

Stock #: 10836

Stock Desc: 2022 TT FOREST RIVER
CHEROKEE 274RK

Chassis #: 4X4TCKC26NX157019

Serial #: 4X4TCKC26NX157019

Mileage: 0

Licence:

Invoice #:

Date In: 27 FEB 23

Promised: 28 FEB 23

Date Sched:

Completed: 21 MAR 23

Warr. Date: 27 MAY 22

Job #1 - Warranty

COMPLAINT: THE FRONT AND REAR SEAL ON THE SLIDE IS RIPPING

CAUSE: front and rear slide room are tore and need new ones

CORRECTION: front and rear slide room are tore and need new ones

BM: INSTALLED NEW SEALS AND A NEW BULB SEAL HAD TO CUT OFF OLD SEALS THAT WAS
TORN AND TRIMED FOR NEW SEAL TO ATTACH TO WALL THEN GLUED THE CORNERS AND
SEALED THE EDGES I SEEN COULPLE OTHER POTS THAT NEEDED SEALER SO I SEALED THOSE
TOO.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	320.00

Parts

Part #	Description	Qty	Price	Total
346810	Seal - Co-Extruded - Wiper - Single - 2" - w/3M Tape - Black	14.00	2.93	41.02
13-1095A	SLIDE ON "D" SEAL X FT.	9.00	2.22	19.98
Subtotal for Job #1:				381.00

Job #2 - Warranty

REAR BUMPPER IS A MESS THE RACK MESSED UP THE BUMPPER

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	33.60
Subtotal for Job #2:			33.60

Job #3 - Warranty

COMPLAINT: THE BED HINDGE IS BROKEN

CAUSE: the bed hinges were missing screws causing it to pop lose and not function right. installed new
screws and tested function several time to make sure it worked

CORRECTION: the bed hinges were missing screws causing it to pop lose and not function right. installed
new screws and tested function several time to make sure it worked



Customer #:
52650

W/O: 69957
Promised Date:
28 FEB 23



Customer #:
52650



Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	32.00
Subtotal for Job #3:			32.00

Job #4 - Warranty

COMPLAINT: THE BLACK GREY AND FRESH TANKS ARE NOT READING RIGHT

CAUSE: black and gray tanks are not reading right as the wires had come loose at board. reattached and ran water. filled tanks to full and then emptied and re did. got same results. re winterized took 2 gals

CORRECTION: black and gray tanks are not reading right as the wires had come loose at board. reattached and ran water. filled tanks to full and then emptied and re did. got same results. re winterized took 2 gals

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	24.00
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	24.00
Subtotal for Job #4:			48.00

Job #22V243 - Warranty

COMPLAINT: RECALL 22V243 LP QUICK CONNECT

CORRECTION: WENT DOWN TO CAMPER AND TOOK PICTURE, REMOVED QUICK DISCONNECT AND INSTALLED NEW ON, DID DROP TEST, ALL GOOD.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	48.00
Subtotal for Job #22V243:			48.00

Parts Total:	61.00
Labour Total:	481.60
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	542.60

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 21 Mar 2023

