

BASDEN RV CENTER, INC D.B.A. AMERICAN RV  
600 E. Baseline Rd.  
Evansville, IN  
US  
47725  
812-867-5200

WARRANTY CLAIM # 69985  
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO  
Customer: 1000 - BASDEN'S AMERICAN RV  
Address: 600 E. BASELINE RD. EVANSVILLE, IN  
USA  
47725  
Phone:  
Stock Number: 11150 - 2023 SPRINGDALE 1800BH 4YDTSGG15PW102364  
VIN: 4YDTSGG15PW102364 HIN: SER#: 4YDTSGG15PW102364  
Mileage: 0 Work Order Comp: 16 MAR 23  
Auth. No: Dealer #: 1194  
Warr. Date: Work Order Date: 02 MAR 23 Inv #: 388538

\*\*\*\*\*

| WO #  | Job # | Description   | JOB INFORMATION |
|-------|-------|---|-----------------|
| 69985 | 1     | BLACK TANK DUMP VALVE HARD TO OPEN CATCHING ON BROKE SEAL<br>BLACK TANK DUMP VALVE HARD TO OPEN AND CLOSE IT WAS CATCHING ON<br>GLUE AND SEAL CASUING IT NOT TO OPEN. IT ASLO TORE SEAL AS WELL.<br>NEEDS NEW DUMP VALVE INSTALLED. REMOVED HARDWARE AND OLD BLACK<br>TANK DUMP VALVE AND INSTALLED NEW AND NEW HARDWARE ALONG WITH NEW<br>SEALS. PUT OLD ONE ON WARRANTY SHELF ALONG WITH ITS HARDWARE.<br>TESTED FUNCTION AND IS WORKING PROPERLY<br>BLACK TANK DUMP VALVE HARD TO OPEN AND CLOSE IT WAS CATCHING ON<br>GLUE AND SEAL CASUING IT NOT TO OPEN. IT ASLO TORE SEAL AS WELL.<br>NEEDS NEW DUMP VALVE INSTALLED. REMOVED HARDWARE AND OLD BLACK<br>TANK DUMP VALVE AND INSTALLED NEW AND NEW HARDWARE ALONG WITH NEW<br>SEALS. PUT OLD ONE ON WARRANTY SHELF ALONG WITH ITS HARDWARE.<br>TESTED FUNCTION AND IS WORKING PROPERLY |                 |
| 69985 | 2     | STEP HITTING DOOR NEEDS ADJUSTED<br>DOOR HITTING STEPS NOT ALLOWING STEPS NOT TO COME DOWN. NEEDS<br>ADJUSTED ADJUSTED STEPS<br>DOOR HITTING STEPS NOT ALLOWING STEPS NOT TO COME DOWN. NEEDS<br>ADJUSTED ADJUSTED STEPS  |                 |
| 69985 | 3     | LIGHT LENS NOT INSTALLED<br>LIGHT LENS ABOVE KITCHEN WAS ON THE COUNTERTOP NEEDED INSTALLED.<br>INSTALLED LIGHT LENS BACK ON<br>LIGHT LENS ABOVE KITCHEN WAS ON THE COUNTERTOP NEEDED INSTALLED.<br>INSTALLED LIGHT LENS BACK ON  |                 |

Claim : 69985

```

*****
WO #      Job #   Description          JOB INFORMATION
*****
69985      4     SHOWER SURROUND NEEDS SEALED
          SHOWER SURROUND NEEDED SEALED UP IN SPOTS. SEALED UP SPOTS
          SHOWER SURROUND NEEDED SEALED UP IN SPOTS. SEALED UP SPOTS

```

```

*****
Part No   Job#   Description          PARTS          Qty   Price   Total
*****
VLPT1003VPM  1   3" WASTE VALVE                1.00  14.50   14.50

```

```

*****
Lab Code  Job#   Description          LABOUR          Hrs   Rate   Total
*****
Z990      1     MISCELLANEOUS REPAIR                0.50  160.00  80.00
Z990      2     MISCELLANEOUS REPAIR                0.01  160.00   1.60
Z990      2     MISCELLANEOUS REPAIR                0.49  160.00  78.40
Z990      3     MISCELLANEOUS REPAIR                0.10  160.00  16.00
Z990      4     MISCELLANEOUS REPAIR                0.30  160.00  48.00

```

```

Parts Total:      14.50
Labour Total:     224.00
Sublet Total:      0.00
Extras Total:      0.00

```

>>>> Claim Total: 238.50

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_