



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69985



CUSTOMER WORK ORDER

WO #: 69985

Customer: 1000 - BASDEN'S

AMERICAN RV -

Tag:

Author: PH

Location: 0316 CHECK PREAUTH

Stock #: 11150

Stock Desc: 2023 TT KEYSTONE

SPRINGDALE 1800BH

Chassis #: 4YDTSGG15PW102364

Serial #: 4YDTSGG15PW102364

Mileage: 0

Licence:

Invoice #:

Date In: 02 MAR 23

Promised:

Date Sched:

Completed: 16 MAR 23

Warr. Date:

Job #SUMMERLAND - Internal

COMPLAINT: SUMMERLAND PDI

CAUSE: PDI ON NEW UNIT

CORRECTION: PDI ON NEW UNIT

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C

Other Services

Code	Description	Qty	Price	Total
LPG	LP GAS	12.00	N/C	N/C
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #SUMMERLAND: 0.00

Job #WINTER - Internal

WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	RAB	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Customer #:
1000



**Job #1 - Warranty**

COMPLAINT: BLACK TANK DUMP VALVE HARD TO OPEN CATCHING ON BROKE SEAL

CAUSE: BLACK TANK DUMP VALVE HARD TO OPEN AND CLOSE IT WAS CATCHING ON GLUE AND SEAL CASUING IT NOT TO OPEN. IT ASLO TORE SEAL AS WELL. NEEDS NEW DUMP VALVE INSTALLED. REMOVED HARDWARE AND OLD BLACK TANK DUMP VALVE AND INSTALLED NEW AND NEW HARDWARE ALONG WITH NEW SEALS. PUT OLD ONE ON WARRANTY SHELF ALONG WITH ITS HARDWARE. TESTED FUNCTION AND IS WORKING PROPERLY

CORRECTION: BLACK TANK DUMP VALVE HARD TO OPEN AND CLOSE IT WAS CATCHING ON GLUE AND SEAL CASUING IT NOT TO OPEN. IT ASLO TORE SEAL AS WELL. NEEDS NEW DUMP VALVE INSTALLED. REMOVED HARDWARE AND OLD BLACK TANK DUMP VALVE AND INSTALLED NEW AND NEW HARDWARE ALONG WITH NEW SEALS. PUT OLD ONE ON WARRANTY SHELF ALONG WITH ITS HARDWARE. TESTED FUNCTION AND IS WORKING PROPERLY

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	80.00

Parts

Part #	Description	Qty	Price	Total
24449	3" WASTE VALVE	1.00	14.50	14.50

Subtotal for Job #1: 94.50**Job #2 - Warranty**

COMPLAINT: STEP HITTING DOOR NEEDS ADJUSTED

CAUSE: DOOR HITTING STEPS NOT ALLOWING STEPS NOT TO COME DOWN. NEEDS ADJUSTED ADJUSTED STEPS

CORRECTION: DOOR HITTING STEPS NOT ALLOWING STEPS NOT TO COME DOWN. NEEDS ADJUSTED ADJUSTED STEPS

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	1.60
Z990	MISCELLANEOUS REPAIR	RAB	78.40

Subtotal for Job #2: 80.00**Job #3 - Warranty**

COMPLAINT: LIGHT LENS NOT INSTALLED

CAUSE: LIGHT LENS ABOVE KITCHEN WAS ON THE COUNTERTOP NEEDED INSTALLED. INSTALLED LIGHT LENS BACK ON

CORRECTION: LIGHT LENS ABOVE KITCHEN WAS ON THE COUNTERTOP NEEDED INSTALLED. INSTALLED LIGHT LENS BACK ON

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	16.00

Subtotal for Job #3: 16.00**Job #4 - Warranty**

COMPLAINT: SHOWER SURROUND NEEDS SEALED

CAUSE: SHOWER SURROUND NEEDED SEALED UP IN SPOTS. SEALED UP SPOTS

CORRECTION: SHOWER SURROUND NEEDED SEALED UP IN SPOTS. SEALED UP SPOTS

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------



Z990 MISCELLANEOUS REPAIR

RAB 48.00

Subtotal for Job #4: 48.00

W/O: 69985



Parts Total: 14.50

Labour Total: 224.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 238.50

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 16 Mar 2023

Customer #:
1000

