



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69998
Promised Date: 24 MAR 23

CUSTOMER WORK ORDER

WO #: 69998
Customer: 1000 - BASDENS
AMERICAN RV -
Tag:
Author: BH
Location: 0314 CHECK PREAUTH

Stock #: 11018
Stock Desc: 2023 TT COACHMEN
CATALINA SUMMIT SERIES 164BH
Chassis #: 5ZT2CAEC9PK005476
Serial #: 5ZT2CAEC9PK005476
Mileage: 0
Licence:

Invoice #:
Date In: 03 MAR 23
Promised: 31 MAR 23
Date Sched:
Completed: 13 MAR 23
Warr. Date:

Job #LPTRAVEL - Internal

COMPLAINT: LP AND SAFETY CHECK ON TRAVEL TRAILER OR FIFTH WHEEL

CAUSE: LP SAFTEY CHCEK ON NEW UNIT

CORRECTION: LP SAFTEY CHCEK ON NEW UNIT

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #LPTRAVEL: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: WINTERIZED UNIT TOOK 1 GAL

CORRECTION: WINTERIZED UNIT TOOK 1 GAL

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	RAB	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Customer #: 1000





Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
Subtotal for Job #WINTER:				0.00

Job #1 - Warranty

COMPLAINT: DOORSIDE COMPARTMENT NEEDS SEALED

CAUSE: DOORSIDE COMPARTMENT WASNT SEALED UP PROPPERLY LEAVING A GAP UP TOP FOR WATER TO GET IN. REMOVED THEIR SLOPPY SEALING JOB CLEANED AND RESEALED

CORRECTION: DOORSIDE COMPARTMENT WASNT SEALED UP PROPPERLY LEAVING A GAP UP TOP FOR WATER TO GET IN. REMOVED THEIR SLOPPY SEALING JOB CLEANED AND RESEALED

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	48.00
Subtotal for Job #1:			48.00

Job #2 - Warranty

COMPLAINT: FRIDGE SWITCH IS LOOSE

CAUSE: FRIDGE SWITCH IS LOSE. WHEN I WENT TO FIX I FOUND THE WIRES WERE BARLEY CONNECTED. REINSTALLED WIRES AND ATTACHED FRIDGE ON AND OFF SWITCH CORRECTLEY

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	16.00
Subtotal for Job #2:			16.00

Job #3 - Warranty

COMPLAINT: BATHROOM DOOR RUBBING CAUSING DOOR NOT TO SHUT RIGHT

CAUSE: BATHROOM DOOR RUBBING AGAINST STRIKE PLATE CAUSING DOOR NOT TO SHUT. ADJUSTED STRIKE PLATE TO ALLOW DOOR TO SHUT RIGHT

CORRECTION: BATHROOM DOOR RUBBING AGAINST STRIKE PLATE CAUSING DOOR NOT TO SHUT. ADJUSTED STRIKE PLATE TO ALLOW DOOR TO SHUT RIGHT

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	16.00
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	16.00
Subtotal for Job #3:			32.00

Job #4 - Warranty

COMPLAINT: BATTON STRIP IN BEDROOM HANGING DOWN

CAUSE: BATTON STRIP IN BEDROOM WAS HANGING DOWN MISSING STAPLES. RESTAPLED AND FILLED IN HOLES

CORRECTION: BATTON STRIP IN BEDROOM WAS HANGING DOWN MISSING STAPLES. RESTAPLED AND FILLED IN HOLES

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	32.00
Subtotal for Job #4:			32.00



W/O: 69998
Promised Date:
31 MAR 23



Parts Total:	0.00
Labour Total:	128.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	128.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 13 Mar 2023

Customer #:
1000

