

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 69999
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11016 - 2023 CATALINA SUMMIT SERIES 164BH 5ZT2CAEC7PK005475
VIN: 5ZT2CAEC7PK005475 HIN: SER#: 5ZT2CAEC7PK005475
Mileage: 0 Work Order Comp: 30 MAR 23
Auth. No: Dealer #:
Warr. Date: Work Order Date: 03 MAR 23 Inv #: 389110

WO # Job # Description JOB INFORMATION

69999 2 LIGHT LENS MISSING ABOVE BUNK
LIGHT LENS ABOVE BUNK MISSING. NEED NEW ONE
LIGHT LENS ABOVE BUNK MISSING. NEED NEW ONE INSTALL LIGHT LENS

69999 1 FRIDGE DOOR TRAY HOLDER CLIP BROKE
FRIDGE DOOR WHRE THE CAN HOLDER GOES THE CLIP IS BROKE/CRACKED ON
THE FRIDGE ITSELF NEEDS NEW ONE
FRIDGE DOOR WHRE THE CAN HOLDER GOES THE CLIP IS BROKE/CRACKED ON
THE FRIDGE ITSELF NEEDS NEW ONE REMOVE MOUNTING SCREW FOR REFER
TO PULL OUT OF CABNET, REMOVE TOP MOUNTING PLATE, REMOVE TOP HING
FOR FREEZER DOO, REMOVE FREZZER DOOR, REMOVE SCRES FOR TOP HING
AND DOOR, GET NEW DOOR, INSTALL NEW DOOR, AND HING, INSTALL NEW
FREEZER DOOR AND HING, INSTALL MOUNTING PLATE, INSTALL REFER BACK
IN CABNET

69999 7 FREEZER DOOR HAS A DENT IN IT
FREEZER DOOR HAS DENT IN IT NEEDS NEW DOOR SEE PICS
FREEZER DOOR HAS DENT IN IT NEEDS NEW DOOR SEE PICS REMOVE
MOUNTING SCREW FOR REFER TO PULL OUT OF CABNET, REMOVE TOP
MOUNTING PLATE, REMOVE TOP HING FOR FREEZER DOO, REMOVE FREZZER
DOOR, REMOVE SCRES FOR TOP HING AND DOOR, GET NEW DOOR, INSTALL
NEW DOOR, AND HING, INSTALL NEW FREEZER DOOR AND HING, INSTALL
MOUNTING PLATE, INSTALL REFER BACK IN CABNET

69999 3 SHOWER SURROUND NEEDS SEALED
SHOWER SURROUND WAS NOT SEALED PROPERLEY. SCRAPED OFF OLD SEALANT

Claim : 69999

 WO # Job # Description JOB INFORMATION

AND SEALED UP

SHOWER SURROUND WAS NOT SEALED PROPERLEY. SCRAPED OFF OLD SEALANT
 AND SEALED UP

69999 4 KITCHEN SINK NEEDS SEALED
 KITCHEN SINK WAS NOT SEALED UP. SEALED UP KITCHEN SINK
 KITCHEN SINK WAS NOT SEALED UP. SEALED UP KITCHEN SINK

69999 5 GFCI OUTLET ON EXTERIOR NEEDS SEALED
 GFCI OUTLET EXTERIOR WASNT SEALED . CLANED URFACED AND SEALED UP
 GFCI OUTLET EXTERIOR WASNT SEALED . CLANED URFACED AND SEALED UP

69999 6 AWNING ARM SCREW BACKING OUT
 AWNING ARM SCREW BACKED OUT CAUSING AWNING WHEN COMING OUT TO
 COLLAPSE. REMOVED SCREW AND INSTALLED A NEW LONGER SCREW
 AWNING ARM SCREW BACKED OUT CAUSING AWNING WHEN COMING OUT TO
 COLLAPSE. REMOVED SCREW AND INSTALLED A NEW LONGER SCREW

 Part No Job# Description PARTS Qty Price Total

 C01297663 2 4.5 INCH LED LIGHT PUCK BASE WITH 1.00 2.19 2.19
 F100282070 1 GE STAINLESS REFER DOOR 2022 MODE 1.00 542.04 542.04
 F100282071 7 GE STAINLESS FREEZER DOOR 2022 | 1.00 397.83 397.83

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.09 160.00 14.40
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.01 160.00 1.60
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.00 160.00 0.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 160.00 0.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 160.00 0.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.20 160.00 32.00
 Z990 7 MISC LABOUR CODE (EXTERNAL) 0.20 160.00 32.00
 Z990 7 MISC LABOUR CODE (EXTERNAL) 0.00 160.00 0.00
 Z990 7 MISC LABOUR CODE (EXTERNAL) 0.00 160.00 0.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.20 160.00 32.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.10 160.00 16.00
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.30 160.00 48.00
 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.50 160.00 80.00

 Excode Job# Description EXTRAS Qty Price Total

 FRT 2 UPS-LIGHT 1.00 19.80 19.80
 FRT 1 UPS DROP SHIP JOBS 1,7 1.00 35.86 35.86

Parts Total: 942.06
 Labour Total: 256.00
 Sublet Total: 0.00
 Extras Total: 55.66

>>>> Claim Total: 1,253.72

Customer Signature: _____

Date: _____

Claim : 69999

```
*****
Excode   Job#   Description      EXTRAS                      Qty    Price    Total
*****
```