



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69999
Promised Date:
24 MAR 23

CUSTOMER WORK ORDER

WO #: 69999

Customer: 1000 - BASDEN'S

AMERICAN RV -

Tag:

Author: BH

Location: 0330 BH TO CLOSE

Stock #: 11016

Stock Desc: 2023 TT COACHMEN

CATALINA SUMMIT SERIES 164BH

Chassis #: 5ZT2CAEC7PK005475

Serial #: 5ZT2CAEC7PK005475

Mileage: 0

Licence:

Invoice #:

Date In: 03 MAR 23

Promised: 31 MAR 23

Date Sched:

Completed: 30 MAR 23

Warr. Date:

Job #LPTRAVEL - Internal

COMPLAINT: LP AND SAFETY CHECK ON TRAVEL TRAILER OR FIFTH WHEEL

CAUSE: LP SAFTEY CHCK ON NEW UNIT

CORRECTION: LP SAFTEY CHCK ON NEW UNIT

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	4.00	N/C	N/C

Subtotal for Job #LPTRAVEL: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER

WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: WINTERIZED UNIT TOOK 1 GAL

CORRECTION: WINTERIZED UNIT TOOK 1 GAL

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	RAB	N/C
Z990	WINTERIZE UNIT	RAB	N/C
Z990	WINTERIZE UNIT	RAB	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C



Customer #:
1000



W/O: 69999
Promised Date:
31 MAR 23



Customer #:
1000



Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
Subtotal for Job #WINTER:				0.00

Job #1 - Warranty

COMPLAINT: FRIDGE DOOR TRAY HOLDER CLIP BROKE

CAUSE: FRIDGE DOOR WHRE THE CAN HOLDER GOES THE CLIP IS BROKE/CRACKED ON THE FRIDGE ITSELF NEEDS NEW ONE

CORRECTION: FRIDGE DOOR WHRE THE CAN HOLDER GOES THE CLIP IS BROKE/CRACKED ON THE FRIDGE ITSELF NEEDS NEW ONE

REMOVE MOUNTING SCREW FOR REFER TO PULL OUT OF CABNET, REMOVE TOP MOUNTING PLATE, REMOVE TOP HING FOR FREEZER DOO, REMOVE FREZZER DOOR, REMOVE SCRES FOR TOP HING AND DOOR, GET NEW DOOR, INSTALL NEW DOOR, AND HING, INSTALL NEW FREEZER DOOR AND HING, INSTALL MOUNTING PLATE, INSTALL REFER BACK IN CABNET

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	32.00

Parts

Part #	Description	Qty	Price	Total
F100282070	GE STAINLESS REFER DOOR 2022 MODEL GPV10FSNSB	1.00	542.04	542.04

Other Services

Code	Description	Qty	Price	Total
FRT	UPS DROP SHIP JOBS 1,7	1.00	35.86	35.86
Subtotal for Job #1:				609.90

Job #2 - Warranty

COMPLAINT: LIGHT LENS MISSING ABOVE BUNK

CAUSE: LIGHT LENS ABOVE BUNK MISSING. NEED NEW ONE

CORRECTION: LIGHT LENS ABOVE BUNK MISSING. NEED NEW ONE
INSTALL LIGHT LENS

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	14.40
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	1.60
Z990	MISC LABOUR CODE (EXTERNAL)		0.00

Parts

Part #	Description	Qty	Price	Total
C01297663	4.5 INCH LED LIGHT PUCK BASE WITH LENS WHITE PUSH BUTTON SWITCH 0016274CW-H	1.00	2.19	2.19

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-LIGHT	1.00	19.80	19.80
Subtotal for Job #2:				37.99





Job #3 - Warranty

COMPLAINT: SHOWER SURROUND NEEDS SEALED

CAUSE: SHOWER SURROUND WAS NOT SEALED PROPERLEY. SCRAPED OFF OLD SEALANT AND SEALED UP

CORRECTION: SHOWER SURROUND WAS NOT SEALED PROPERLEY. SCRAPED OFF OLD SEALANT AND SEALED UP

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	32.00
Subtotal for Job #3:			32.00

Job #4 - Warranty

COMPLAINT: KITCHEN SINK NEEDS SEALED

CAUSE: KITCHEN SINK WAS NOT SEALED UP. SEALED UP KITCHEN SINK

CORRECTION: KITCHEN SINK WAS NOT SEALED UP. SEALED UP KITCHEN SINK

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	16.00
Subtotal for Job #4:			16.00

Job #5 - Warranty

COMPLAINT: GFCI OUTLET ON EXTERIOR NEEDS SEALED

CAUSE: GFCI OUTLET EXTERIOR WASNT SEALED . CLANED URFACED AND SEALED UP

CORRECTION: GFCI OUTLET EXTERIOR WASNT SEALED . CLANED URFACED AND SEALED UP

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	48.00
Subtotal for Job #5:			48.00

Job #6 - Warranty

COMPLAINT: AWNING ARM SCREW BACKING OUT

CAUSE: AWNING ARM SCREW BACKED OUT CAUSING AWNING WHEN COMING OUT TO COLLAPSE. REMOVED SCREW AND INSTALLED A NEW LONGER SCREW

CORRECTION: AWNING ARM SCREW BACKED OUT CAUSING AWNING WHEN COMING OUT TO COLLAPSE. REMOVED SCREW AND INSTALLED A NEW LONGER SCREW

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	80.00
Subtotal for Job #6:			80.00

Job #7 - Warranty

COMPLAINT: FREEZER DOOR HAS A DENT IN IT

CAUSE: FREEZER DOOR HAS DENT IN IT NEEDS NEW DOOR SEE PICS

CORRECTION: FREEZER DOOR HAS DENT IN IT NEEDS NEW DOOR SEE PICS
 REMOVE MOUNTING SCREW FOR REFER TO PULL OUT OF CABNET, REMOVE TOP MOUNTING



PLATE, REMOVE TOP HING FOR FREEZER DOO, REMOVE FREZZER DOOR, REMOVE SCRES FOR
TOP HING AND DOOR, GET NEW DOOR, INSTALL NEW DOOR, AND HING, INSTALL NEW FREEZER
DOOR AND HING, INSTALL MOUNTING PLATE, INSTALL REFER BACK IN CABNET

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	32.00
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)		0.00

Parts

Part #	Description	Qty	Price	Total
F100282071	GE STAINLESS FREEZER DOOR 2022 FOR MODEL GPV10FSNSB	1.00	397.83	397.83

Subtotal for Job #7: 429.83

Parts Total: 942.06
Labour Total: 256.00
Sublet Total: 0.00
Extras Total: 55.66
WORK ORDER TOTAL: 1,253.72

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited
to work performed. Consequential damages are not covered. All guaranteed work
must be completed in our service department.

Customer Signature : _____

Date: 30 Mar 2023

W/O: 69999
Promised Date:
31 MAR 23



Customer #:
1000

