

WARRANTY CLAIM # 70003
MANUFACTURER'S CLAIM #:

Phone: _____
 Stock Number: 10874 - 2023 CHEROKEE 306MM 4X4TCKG20PX161435
 VIN: 4X4TCKG20PX161435 HIN: _____ SER#: 4X4TCKG20PX161435
 Mileage: 0
 Auth. No: _____ Work Order Comp: 31 MAR 23
 Warr. Date: _____ Dealer #: _____
 _____ Work Order Date: 03 MAR 23 Inv #: 389384

WO #	Job #	Description	JOB INFORMATION
70003	6	KITCHEN SLIDEROOM BLIND BROKEN INSTALLED NEW ZEBRA BLINDS INSTALLED NEW ZEBRA BLINDS	
70003	1	STEPS HITTING FRAME REAR ENTRY STEPS WERE HITTING DOOR FRAME CAUSING STEPS NOT TO GO DOWN. NEEDS ADJUSTED REAR ENTRY STEPS WERE HITTING DOOR FRAME CAUSING STEPS NOT TO GO DOWN. NEEDS ADJUSTED. ADJUSTED STEPS TO ALLOW THEM TO COME DOWN	
70003	2	OUTSIDE KITCHEN PLATFORM FOR THE STOVE NOT ATTACHED ALL THE WAY OUTSIDE KITCHEN WAS NOT ATTACHED RIGHT HAD TO ADD SCREWS AND SECURE OUTSIDE KITCHEN WAS NOT ATTACHED RIGHT HAD TO ADD SCREWS AND SECURE	
0003	3	REAR A/C FLUSHING E3 CODE REAR AC UNIT WAS FLASHING E3 CODE . REMOVED THERMOSAT AND FOUND NOTHING WRONG . WENT TO AC PLENUM REMOVED COVER AND FOUND WIRES NOT ATTACHED FROM THE FACTORY. STRIPPED BACK WIRES AND CRIMPPED NEW CONNECTOR THEN TESTED AC UNIT. REAR AC UNIT WAS FLASHING E3 CODE . REMOVED THERMOSAT AND FOUND NOTHING WRONG . WENT TO AC PLENUM REMOVED COVER AND FOUND WIRES NOT ATTACHED FROM THE FACTORY. STRIPPED BACK WIRES AND CRIMPPED NEW CONNECTOR THEN TESTED AC UNIT.	

Claim : 70003

 WO # Job # Description JOB INFORMATION *****

70003 4 SHOWER SURROUND NEEDS SEALED
 SHOWER SURROUND WAS NOT SEALED UP NEEDED SEALED UP
 SEALED UP SHOWER SURROUND

70003 5 DRAWER IN KITCHEN RUBBING
 DRAWER IN KITCHEN RUBBING AGAINST LOSE SCREW CAUSING DRAWER NOT
 TO OPEN ALL THE WAY. REEMOVED DRAWER AND TIGHTENED SCREW UP AND
 REINSTALLED DRAWER AND THEN TESTED DRAWER
 DRAWER IN KITCHEN RUBBING AGAINST LOSE SCREW CAUSING DRAWER NOT
 TO OPEN ALL THE WAY. REEMOVED DRAWER AND TIGHTENED SCREW UP AND
 REINSTALLED DRAWER AND THEN TESTED DRAWER

 Part No Job# Description PARTS Qty Price Total *****

 F100140433 6 SHADE, 64" X 38" ZEBRA SHADE 1.00 89.00 89.00

 Lab Code Job# Description LABOUR Hrs Rate Total *****

 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.20 160.00 32.00
 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.00 160.00 0.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.10 160.00 16.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.10 160.00 16.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.15 160.00 24.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.15 160.00 24.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.30 160.00 48.00
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.20 160.00 32.00

 Excode Job# Description EXTRAS Qty Price Total *****

 FRT 6 UPS-SHADE 1.00 32.07 32.07

Parts Total: 89.00
 Labour Total: 192.00
 Sublet Total: 0.00
 Extras Total: 32.07

>>>> Claim Total: 313.07

Customer Signature: _____

Date: _____