

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 70004
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11193 - 2023 CATALINA 263FKDSLE 5ZT2CARB8PX028638
VIN: 5ZT2CARB8PX028638 HIN: SER#: 5ZT2CARB8PX028638
Mileage: 0 Work Order Comp: 16 MAR 23
Auth. No: Dealer #:
Warr. Date: Work Order Date: 03 MAR 23 Inv #: 388536

WO # Job # Description JOB INFORMATION

70004 1 BLACK TANK LEAKING
WHEN DOING THE PDI FILLED ALL TANKS TO CHECK THE GAUGES FOR
PROPER WATER LEVEL. CHECKED CAMPER ALL OVER FOR LEAKS AND NOTICED
THE BLACK TANK IS LEAKING. THE UNDER BELLY HAS A LOT OF
UNDERBELLY TAPE PATCHES.TOOK PICTURES OF THE LEAK. CUT THE
UNDERBELLY AROUND THE BLACK TANK DRAIN. THE DRAIN WAS NOT GLUED
PROPER AT THE ELBOW CAUSING A LEAK. REMOVED THE BAD DRAIN PIPE
FROM TANK. GOT AN NEW ELBOW, FANGE AND PIPE TO MAKE A NEW DRAIN.
CLEANED AND GLUED NEW PIECES TOGETHER THEN ATTACHED TO THE BLACK
TANK. PUT NEW UNDERBELLY TAPE ON UNDERBELLY AFTER FILLING TANK
FULL WITH WATER TO MAKE SURE IT DIDNT LEAK. NOTICED WHEN BRINGING
IN CAMPER TO SERVICE BAY THE CAP FOR THE BLACK TANK DRAIN WAS
MISSING OFF THE PIPE. THE LANYARD CORD HAD BROKEN OFF THE
CAP.REPLACED CAP WITH NEW CAP.

70004 2 TV OUTLET READING REVERSED ON TESTER
TV OUTLET IN LIVING ROOM WAS HOOKED UP WRONG
TOOK PICTURE OF TV OUTLET THAT WAS HOOKED UP BACKWARDS.
DISCONNECTED THE SHORE POWER. REMOVED THE OUTLET FROM WALL. THEN
REMOVED THE COVER OFF THE BACK. TOOK PICTURE OF WIRES. REMOVED
WIRES FROM OUT LET AND PUT IN PROPER ORDER. THEN TOOK MORE
PICTURES. PUT OUTLET BACK IN WALL THEN HOOKED SHORE POWER BACK UP
TO TEST CONNECTION.CHECKED OUTLET AGAIN FOR PROPER CONNECTION
WITH TESTER.

Part No Job# Description PARTS Qty Price Total

LSB66V13 1 3" ANONDA SLIP SOCKET 1.00 3.09 3.09

Claim : 70004

```

*****
Part No      Job#  Description      PARTS      Qty      Price      Total
*****
11-1111      1    3" LONG SWEEP BEND      1.00      10.19      10.19
CMC39462     1    SEWER CAP W/ HOSE CONNECTION  1.00      4.03      4.03

```

```

*****
Lab Code     Job#  Description      LABOUR      Hrs      Rate      Total
*****
Z990         1    MISC LABOUR CODE (EXTERNAL)  0.60      160.00      96.00
Z990         2    MISC LABOUR CODE (EXTERNAL)  0.20      160.00      32.00

```

```

Parts Total:      17.31
Labour Total:      128.00
Sublet Total:      0.00
Extras Total:      0.00

```

```

>>>> Claim Total:      145.31

```

Customer Signature: _____

Date: _____