



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70005



CUSTOMER WORK ORDER

WO #: 70005

Customer: 1000 - BASDEN'S

AMERICAN RV -

Tag:

Author: PH

Location: 0320 CHECK PREAUTH

Stock #: 11019

Stock Desc: 2023 TT COACHMEN

CATALINA 323BHDSCLE

Chassis #: 5ZT2CAXB8PX028710

Serial #: 5ZT2CAXB8PX028710

Mileage: 0

Licence:

Invoice #:

Date In: 03 MAR 23

Promised:

Date Sched:

Completed: 20 MAR 23

Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: PDI - PDI NEW TRAVEL TRAILER.

CORRECTION: Installed new battery box. Shortened battery cables to fit. Filled LP tanks. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 65 psi. Checked roof and awning. Checked all stab jacks. Checked both entrance doors and all compartment doors. Checked all interior lights. Checked power cord. Checked all electrical outlets and GFCI outlets. Checked all USB outlets. Checked all cabinets and drawers. Checked all windows and blinds. Checked converter output. Added water to fresh water tank. Flushed antifreeze from all water lines and faucets. Checked all water lines and faucets for leaks. Outside kitchen sink drain leaking. Removed drain fitting. Checked seal. Seal OK. Applied lube to flat seal and reinstalled drain fitting. Tested for water leak again. Ran water several mins. No leak found this time. Opened by-pass on water heater and filled. Purged air from system. Filled all holding tanks and checked monitor panel. Performed LP drop test and set LP pressure at 10 in.wc. Applied all company decals. Checked operation of Back-up camera. Had to pair camera and monitor together. Moved unit back to sales lot.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED



Customer #:
1000



NUMBER OF GALLONS USED _____

CAUSE: WINTER - WINTERIZE UNIT AND DRAIN ALL HOLDING TANKS.

CORRECTION: By-passed water heater. Blew out all water lines and faucets. Added antifreeze to all water lines and faucets, including outside kitchen and outside shower. Poured antifreeze in all drain traps. Drained all holding tanks, including water heater.

Labor			
Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	DKM	N/C
Z990	WINTERIZE UNIT	DKM	N/C

Parts				
Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C
10-0858	1pk 1/2"x 1/2" BARB ADPT.	1.00	N/C	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: TV WONT PICK UP CHANNELS

CAUSE: TV WONT PICK UP CHANNELS.

CORRECTION: Checked all coax cables. Coax cable from TV booster to Roof antenna shows SHORT. Removed antenna from roof. Center coax shorted. Installed new cable end. Moved unit outside and ran channel scan. Picked up channels.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	48.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	80.00

Subtotal for Job #1: 128.00

Job #2 - Warranty

COMPLAINT: NO POWER TO FIREPLACE RECEPTICLE

CAUSE: NO POWER TO FIREPLACE RECEPTICAL.

CORRECTION: See Job # 3. Fireplace and water heater are on same leg of 50 Amp. Fireplace now working.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	0.00

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: WATER HEATER DOES NOT WORK ON ELE

CAUSE: WATER HEATER DOES NOT WORK ON ELECTRIC.

CORRECTION: Water does not work on Electric. Removed heating element cover to check all connections. All connections good. Replaced cover. Removed junction box cover on water heater. All connections good. Remounted junction box cover. Removed converter cover. Checked all connections on breakers. All tight. Closer inspection showed Black wire side of 50 amp was not completely installed in circuit breaker. Loosened breaker screw and shoved wire into breaker all the way. Checked power at water heater. Now has power. Remounted breaker panel cover.

W/O: 70005



Customer #: 1000



Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	240.00

Subtotal for Job #3: 240.00

Parts Total: 0.00
Labour Total: 368.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 368.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 20 Mar 2023

W/O: 70005



Customer #:
1000

