



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70028
Promised Date:
24 MAR 23

CUSTOMER WORK ORDER

WO #: 70028

Customer: 40505 - MULLEN, RICHARD
- 812-589-6698

Tag:

Author: BH

Location: 0309 CHECK PREAUTH

Stock #: 10707

Stock Desc: 2022 TT KEYSTONE
SPRINGDALE 266RL

Chassis #: 4YDTSGL28N3104526

Serial #: 4YDTSGL28N3104526

Mileage:

Licence:

Invoice #:

Date In: 06 MAR 23

Promised: 31 MAR 23

Date Sched:

Completed: 09 MAR 23

Warr. Date: 28 FEB 22

Job #1 - Warranty

COMPLAINT: LP DETECTOR IS GOING OFF ALL THE TIME

CAUSE: PULLED UNIT INTO SHOP AND PLUGGED INTO SHORE POWER. L.P. DETECTOR IS BEEPING RANDOMLY. DETECTOR WILL NOT PERFORM TEST FUNCTION. IT BEEPS ONCE THEN DOES NOTHING. THERE IS NO LIGHT PRESENT ON DETECTOR AS WELL. NEED TO REPLACE.

CORRECTION: REMOVED MOUNTING SCREWS. CUT WIRES. REMOVED DAMAGED DETECTOR. INSTALLED NEW DETECTOR TO WIRES AND SECURED TO WALL. PARKED UNIT.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	80.00

Parts

Part #	Description	Qty	Price	Total
636092	Alarm - LP/CO - Combo - Detector - 12V - 2 Wire - Surface Mount - Black	1.00	43.46	43.46

Subtotal for Job #1: 123.46

Parts Total: 43.46
Labour Total: 80.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 123.46

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 09 Mar 2023



Customer #:
40505