



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70074

CUSTOMER WORK ORDER

WO #: 70074
Customer: 1000 - BASDEN'S
AMERICAN RV -
Tag:
Author: PH
Location: 0329 CHECK PREAUTH

Stock #: 10739
Stock Desc: 2023 TT COACHMEN
CATALINA 263BHSCLE
Chassis #: 5ZT2CARBXPU041750
Serial #: 5ZT2CARBXPU041750
Mileage: 0
Licence:

Invoice #:
Date In: 13 MAR 23
Promised:
Date Sched:
Completed: 28 MAR 23
Warr. Date:



Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CORRECTION: i clocked in on this job number at 8:07 by mistake it should have been under job number 70154. i switched over to fixing the drawers at 11:17 did pdi on new travel trailer

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DWW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DWW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DWW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DWW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DWW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DWW	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: SCREEN DOOR NEEDS ADJUSTED

CORRECTION: ADJUSTED SCREEN DOOR LATCH AND HANDLE

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	32.00

Subtotal for Job #1: 32.00

Job #2 - Warranty

COMPLAINT: ENTRY DOOR NEEDS ADJUSTED

CORRECTION: SPRAY LUBE IN PLUNGER ON DOOR, AND ADJUSTED STRIKE PLATE

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	32.00

Customer #: 1000



Subtotal for Job #2: 32.00

Job #3 - Internal

COMPLAINT: REMOVE EXCESS SEALER AROUND UNIT

CORRECTION: REMOVED SILCONE FROM SEVERAL PLACES ON UNIT . I USED HEAT GUN AND A PUTTY BUDDY. THEN CLEANED AREAS WITH SPIRITS

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	N/C

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: THE KITCHEN SINK IS LEAKING

CORRECTION: PICS ON ONE DRIVE. THE RUBBER GASKET FOR THE STRAINER BASKET WAS UNDERNEITH THE SINK INSTEAD OF ON TOP BETWEEN BASKET AND SINK

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	96.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	0.00

Subtotal for Job #4: 96.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CORRECTION: WINTERIZED UNIT. DRAINED ALL TANKS. USED 2 GALLONS OF ANTIFREEZE

Labor Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	DWW	N/C

Parts Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Parts Total: 0.00
Labour Total: 160.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 160.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.



Customer #: 1000



Customer Signature : _____

Date: 28 Mar 2023

W/O: 70074



Customer #:
1000

