



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70149
Promised Date:
21 MAR 23

CUSTOMER WORK ORDER

WO #: 70149

Customer: 1000 - BASDEN'S
AMERICAN RV -

Tag:

Author: PH

Location: 0331 CHECK STATUS WITH
JP

Stock #: 11258

Stock Desc: 2023 TT FOREST RIVER
CHEROKEE GREY WOLF 26DJSE

Chassis #: 5ZT2CKRB0PF004460

Serial #: 5ZT2CKRB0PF004460

Mileage: 0

Licence:

Invoice #:

Date In: 22 MAR 23

Promised: 31 MAR 23

Date Sched:

Completed: 30 MAR 23

Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: PDINTT - PDI NEW TRAVEL TRAILER.

CORRECTION: Moved unit into shop from sales lot. Filled LP tanks. Removed factory battery and battery box. Added drain holes in bottom of box. Relocated box to center of frame. Reinstalled battery and connected battery cables. Secured battery cables. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 65 psi. Operated all stab jacks. Checked awning. Checked entrance door and all compartment doors. Checked foldout steps. Checked all interior lights. Checked all windows and blinds. Checked all cabinets and drawers. Checked all USB outlets. Applied all company decals. Added water to fresh water tank and flushed antifreeze from all water lines and faucets. Checked all water lines and faucets for leaks. Purged all air from water system. Performed LP drop test and set LP pressure at 10 1/2 in.wc. Checked operation of all appliances. Checked Radio. Took pictures and recorded all model and serial numbers. Filled all holding tanks and checked monitor panel. Connected to air pressure and blew out all water lines and faucets. Added antifreeze to all water lines and faucets, including outside shower. Poured antifreeze in all drain traps. Checked TV antenna. Checked inside and outside locations. Both OK. Drained all holding tanks. Moved unit back to sales lot waiting on parts to come in.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: WINTERIZED UNIT



Customer #:
1000



W/O: 70149
Promised Date:
31 MAR 23



Customer #:
1000



Labor				
Code	Description		Mechanic	Total
Z990	WINTERIZE UNIT		JP	N/C
Parts				
Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C
Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
Subtotal for Job #WINTER:				0.00

Job #1 - Warranty

COMPLAINT: FOUR RECEPTICLES ON GFI SHOW OPEN NEUTRAL

CAUSE: FOUR RECEPTICALS ON GFIC SHOW OPEN NEUTRAL.

CORRECTION: Removed the two recepticals by kitchen sink. Removed back of both recepticals. Found the closest to window had a neutral wire was not pushed down into groove to make contact. Pushed wire into groove and checked receptical. Now receptical is good and other three are good also.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	96.00
Subtotal for Job #1:			96.00

Job #2 - Warranty

COMPLAINT: INVERTER IN FRONT BEDROOM HAS OPEN GROUND

CAUSE: INVERTER IN FRONT BEDROOM HAS OPEN GROUND.

CORRECTION: No literature in packet for this option. Removed from wall to check wiring. Only two 12 volt wires go to it. This inverter is a charge station for a cell phone. Only 5.3 volts. Remounted on wall. put a label in it to read "CELL PHONE ONLY".

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	64.00
Subtotal for Job #2:			64.00

Job #3 - Warranty

COMPLAINT: LATCH BROKEN ON WATER HEATER DOOR

CAUSE: LATCH IS BROKEN ON DOOR

CORRECTION: DOOR AND FRAME IS INSTALLED CROOKED AND LATCH IS BROKRN, USE HEAT GUN TO SOFTEN GEOCEL, USE HEAT GUN AND PLASTIC PUTTY KNIFE TO GET SEALER OFF OF METAL, INSTALL NEW DOOR AND FRAME, TAPE OFF AROUND DOOR AND RESEAL, PUT UNIT OUT ON LOT

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		JP	32.00
Parts				
Part #	Description	Qty	Price	Total
F100345503	WATER HEATER, 15" X 15" HINGED DOOR ONLY - BLACK, FOR FURRION 2.4 GPM (BULK RACK 2 SHELF 2 SIDE B)	1.00	23.24	23.24
90M13170A	GEOCEL 2300 CLEAR SEALANT	1.00	7.48	7.48



W/O: 70149
Promised Date:
31 MAR 23



Customer #:
1000



Other Services

Code	Description	Qty	Price	Total
FRT	UPS- JOBS 3 & 4	1.00	19.85	19.85
Subtotal for Job #3:				82.57

Job #4 - Warranty

COMPLAINT: OFF DOOR SIDE SWITCH NOT WORKING

CORRECTION: FIND TRAILER ON SALES LOT AND CLOSE UP AND PULL IN, FOUND NO POWER TO LIGHT, TRACED BACK AND FOUND LIGHT HAS 2 SWITCHES IN LINE ONE AT LIGHT AND ONE ON MONITOR PANEL WITH BOTH SWITCHES ON LIGHT WORKS
NO NOTES IN TICKET ON WHY LIGHT WAS ORDERED, WAS TOLD TO CHANGE LIGHT SEE DM

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	32.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00

Parts

Part #	Description	Qty	Price	Total
F100214327	LIGHT, PORCH LIGHT AT UTILITY CENTER, LED ANGLED 12 DIODE - BLACK W/ SWITCH (II31, II33, II34, II35, JJ35, JJ42)	1.00	4.06	4.06

Subtotal for Job #4: 36.06

Job #5 - Warranty

COMPLAINT: ROOF VENT CAP COMING OFF

CAUSE: ROOF VENT CAP COMING OFF.

CORRECTION: Vent cap coming off because vent pipe is sticking up too much to allow cap to be mounted correctly. Removed mounting screw. Cut 1" from end of vent pipe to allow cap to sit down on base. Reattached vent cap and sealed screw.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	80.00

Subtotal for Job #5: 80.00

Parts Total: 34.78
Labour Total: 304.00
Sublet Total: 0.00
Extras Total: 19.85
WORK ORDER TOTAL: 358.63

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 30 Mar 2023

