



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70246
Promised Date: 29 APR 23

CUSTOMER WORK ORDER

WO #: 70246
Customer: 1000 - BASDEN'S
AMERICAN RV -
Tag:
Author: BH
Location: 0412 BH TO CLOSE

Stock #: 11264
Stock Desc: 2023 TT COACHMEN
CATALINA 283RKSLE
Chassis #: 5ZT2CATB3PX028913
Serial #: 5ZT2CATB3PX028913
Mileage: 0
Licence:

Invoice #:
Date In: 03 APR 23
Promised: 29 APR 23
Date Sched:
Completed: 12 APR 23
Warr. Date:



Customer #:
1000



Job #PDINTT - Internal PDI - NEW TRAVEL TRAILER

Labor Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C
500627	CLEAR SIKASIL PLUS	1.00	N/C	N/C

Other Services Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: BATHROOM DOOR RUBBING

CAUSE: BATHROOM DOOR RUBBING AGAINST STRIKE PLATE. STRIKE PLATE NEEDS ADJUSTED. LOSSENNED SCREWS AND READJUSTED STRIKE PLATE TO ALLW DOOR TO SHUT PROOPERLEY AND NOT RUB

CORRECTION: BATHROOM DOOR RUBBING AGAINST STRIKE PLATE. STRIKE PLATE NEEDS ADJUSTED. LOSSENNED SCREWS AND READJUSTED STRIKE PLATE TO ALLW DOOR TO SHUT PROOPERLEY AND NOT RUB

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	32.00

Subtotal for Job #1: 32.00





Job #2 - Warranty

COMPLAINT: BEDROOM DRAWER NOT SHUTTING

CAUSE: BEDROOM DRAWER NUT SHUUTING AS IT WAS OFF THE TRACK. REINSTALLLE
PROPERELY ON THE TRACK THEN TESTED

CORRECTION: BEDROOM DRAWER NUT SHUUTING AS IT WAS OFF THE TRACK. REINSTALLLE
PROPERELY ON THE TRACK THEN TESTED

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	16.00
Subtotal for Job #2:			16.00

Job #3 - Warranty

COMPLAINT: SHOWER SURROUND NEEDS SEALED

CAUSE: shower surround needed sealed up on top. sealed up shower surround with clear silicone

CORRECTION: shower surround needed sealed up on top. sealed up shower surround with clear silicone

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	24.00
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	0.00
Subtotal for Job #3:			24.00

Job #4 - Warranty

COMPLAINT: KITCHEN SINK DRAIN PIPE NOT CONNECTED

CAUSE: KITCHEN SINK DRAIN PIPE WASNT SCREWED ON FROM FACTORY, CAUSING A LEAK
WHEN RUNNING WATER. REATTACHED FITTING AND TESTED

CORRECTION: KITCHEN SINK DRAIN PIPE WASNT SCREWED ON FROM FACTORY, CAUSING A
LEAK WHEN RUNNING WATER. REATTACHED FITTING AND TESTED

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	48.00
Subtotal for Job #4:			48.00

Job #5 - Warranty

COMPLAINT: FREEZER DOOR HITTING LATCH

CAUSE: FREEZER DOOR HITTING LATCH WHEN YOU GO TO CLOSE IT. LATCH NEEDS TO BE
ADJUSTED DOWN. ADJUSTED LATCH DOWN SO THAT FREEZER DOOR CAN SHUT PROPERLEY

CORRECTION: FREEZER DOOR HITTING LATCH WHEN YOU GO TO CLOSE IT. LATCH NEEDS TO
BE ADJUSTED DOWN. ADJUSTED LATCH DOWN SO THAT FREEZER DOOR CAN SHUT
PROPERLEY

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	32.00
Subtotal for Job #5:			32.00

Job #6 - Warranty

COMPLAINT: FRIDGE SWITCH NOT ATTACHED

CAUSE: fridge switch was not attached all the way. reattached switch properley and tested



CORRECTION: fridge switch was not attached all the way. reattached switch properly and tested

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	8.00
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	0.00
Subtotal for Job #6:			8.00

Parts Total: 0.00
Labour Total: 160.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 160.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 12 Apr 2023

Customer Signature : _____

W/O: 70246
Promised Date:
29 APR 23



Customer #:
1000

