



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70267
Promised Date:
28 APR 23

CUSTOMER WORK ORDER

WO #: 70267 (Appointment Date: 04 APR 2023 - Time: 05:00pm)

Customer: 1000 - BASDEN'S

AMERICAN RV -

Tag:

Author: BJW

Location: 0502 CHECK STATUS WITH

BB

Stock #:

Stock Desc: 2022 TT KEYSTONE

SPRINGDALE 1740RK

Chassis #: 4YDTSGG19NW109167

Serial #: 4YDTSGG19NW109167

Mileage: 0

Licence:

Invoice #:

Date In: 04 APR 23

Promised: 29 APR 23

Date Sched:

Completed: 28 APR 23

Warr. Date: 16 MAY 22

Job #1 - Warranty

COMPLAINT: THERE IS A LARGE AMOUNT OF WATER IN THE AREA OF THE MURPHY BED. THE MATTRESS IS SOAKED AND MOLDING. AND THE CARPET IS WET AND MOLDING. CUSTOMER HAS NOTICED THAT THE PASS THROUGH IS DRY. THERE IS MOLD GROWING UP THE WALL AS WELL

CORRECTION: AFTER CHECKING OUT THE ROOF, FOUND A FEW SPOTS THAT I HAD TO DICOR. TOOK PICS. FRONT TRIM AROUND SATILITE AND REAR TRIM. TOOK PICS OF THE BED. NEED TO TAKE OUT 12V AND 110 ON LOWER CABINETS. NEED TO REMOVE ALL THE CABINETS BY THE BED. REMOVE WALL PANELS. CUT AND INSTALL WALL PANELS AND BATON STRIPS. REMOVE BED AND FRAME. REMOVE SHELF AND BOTH CABINETS AND LOWER CABINETS. CUT OUT DAMAGED WALL PANELS. PUT BLOCKING IN WHERE NEEDED. INSTALL NEW WALL PANELS. CUT NEW SIDES FOR CABINET. PUT CABINETS BACK. CUT TRIM FOR SEAMS. PUTTY HOLES. PUT BED FRAME BACK. PUT NEW BED ON FRAME

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BB	320.00
Z990	MISCELLANEOUS REPAIR	BB	320.00
Z990	MISCELLANEOUS REPAIR	BB	0.00
Z990	MISCELLANEOUS REPAIR	BB	0.00
Z990	MISCELLANEOUS REPAIR		0.00
Z990	MISCELLANEOUS REPAIR	BB	160.00
Z990	MISCELLANEOUS REPAIR	BB	480.00
Z990	MISCELLANEOUS REPAIR	BB	0.00
Z990	MISCELLANEOUS REPAIR	BB	640.00

Parts

Part #	Description	Qty	Price	Total
681466	Trim - Batten - 3.6mm x 7/8" x 96" - Carb	6.00	2.23	13.38
	2 - LN - Bev x 2 - Uni Mat Grey			
681467-KEY	Panel - 3.6mm x 48" x 96" - Carb 2 - LN	3.00	52.99	158.97
	- Uni Mat Grey			
673442	Mattress - Folding - 6" x 59" x 27" TH -	1.00	315.41	315.41
	6" x 59" x 24" BH - 6" x 59" x 24" - 1S ST			
	- Serta Baylis/Serta Blue FR			

Other Services

Code	Description	Qty	Price	Total
FRT	UPS FREIGHT-PANELS & TRIM	0.00	0.00	0.00
FRT	UPS FREIGHT-MATTRESS	1.00	109.71	109.71

Subtotal for Job #1: 2,517.47



Customer #:
1000



W/O: 70267
Promised Date:
29 APR 23



Customer #:
1000



Job #2 - Warranty

COMPLAINT: WATER RUNS DOWN BETWEEN THE AWNING AND THE COACH WHEN IT IS RAINING.

CORRECTION: PUT SILICONE OVER SCREW ON AWNING. TOOK PICS

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BB	16.00
Z990	MISCELLANEOUS REPAIR	BB	0.00

Parts

Part #	Description	Qty	Price	Total
13-1320	PW HAPS FREE SELF-LEVELING DICOR	3.00	6.33	18.99

Subtotal for Job #2: 34.99

Job #3 - Internal

COMPLAINT: UNDERBELLY IS COMING LOOSE AGAIN ON THE FRONT

CORRECTION: PUT EXTREAM TAPE ON BOTTOM FRONT UNDER DIAMOND PLATE

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Subtotal for Job #3: 0.00

Parts Total: 506.75
Labour Total: 1,936.00
Sublet Total: 0.00
Extras Total: 109.71
WORK ORDER TOTAL: 2,552.46

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 28 Apr 2023

