

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 70309
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 29507 - BRIAN SMITH
Address: 4866 SALEM DR. NEWBURGH, IN

47630

Phone: 812-629-6468

Stock Number: 11162 - 2022 MONTANA 3761FL 4YDFM0T24N4701973

VIN: 4YDFM0T24N4701973 HIN:

SER#: 4YDFM0T24N4701973

Mileage: 0

Work Order Comp: 18 APR 23

Auth. No:

Dealer #: 1194

Warr. Date: 25 MAR 23

Work Order Date: 08 APR 23

Inv #: 389925

WO # Job # Description JOB INFORMATION

70309 1 CUSTOMER NOTICES WATER LEAK FROM SINK FITTING IN HALF BATH.
CUSTOMER STATES IT MAY BE UP IN THE ACTUAL VALVE
CUSTOMER NOTICES WATER LEAK FROM SINK FITTING IN HALF BATH.
CUSTOMER STATES IT MAY BE UP IN THE ACTUAL VALVE.
Checked both water line connections. Both tight and not
leaking. Water is leaking down from inside faucet housing.
Removed faucet and checked for cut braided lines. Could not
find any. Water dripping from higher inside faucet. 4/11/2023:
Turned in parts request for a new faucet.

70309 2 THE BLOWER MOTOR ON THE FURNACE SOUNDS AS THOUGH IT MAY BE OFF
BALANCE. SAYS IT HAS A VIBRATION
THE BLOWER MOTOR ON THE FURNACE SOUNDS AS THOUGH IT MAY BE OFF
BALANCE. SAYS IT HAS A VIBRATION.
Removed furnace from unit. Bench tested to find vibration.
Could not find a vibration. Cleaned all old silicone from
furnace and mounting ring. Set furnace back inside unit. Ran
furnace without installing mounting ring. Furnace has a
vibration. Checked vanes on blower wheel. About (5) of them are
warped on one end. Blower wheel needs replaced. 4/11/2023:
Turned in parts request for a new blower wheel.

70309 7 SCREEN DOOR NOT LATCHING PROPERLY, NEEDS ADJUSTED
SCREEN DOOR NOT LATCHING PROPERLY, NEEDS ADJUSTED.
Adjusted latch on screen door to latch properly. Screen door now
opens and closes by itself and with entrance door.

Claim : 70309

```

*****
WO #      Job #   Description      JOB INFORMATION
*****

```

```

*****
Part No   Job#   Description      PARTS      Qty      Price      Total
*****
679311    1   Faucet - Kitchen - High Rise - Ve  1.00     55.89     55.89
41-1880   2   33126 BLOWER WHEEL                1.00     20.08     20.08

```

```

*****
Lab Code  Job#   Description      LABOUR      Hrs      Rate      Total
*****
Z990      1   MISCELLANEOUS REPAIR                0.00     160.00      0.00
Z990      1   MISCELLANEOUS REPAIR                0.50     160.00     80.00
Z990      2   MISCELLANEOUS REPAIR                1.25     160.00    200.00
Z990      2   MISCELLANEOUS REPAIR                0.00     160.00      0.00
Z990      2   MISCELLANEOUS REPAIR                0.00     160.00      0.00
Z990      2   MISCELLANEOUS REPAIR                0.00     160.00      0.00
Z990      7   MISCELLANEOUS REPAIR                0.00     160.00      0.00
Z990      7   MISCELLANEOUS REPAIR                0.00     160.00      0.00
Z990      7   MISCELLANEOUS REPAIR                0.20     160.00     32.00

```

```

*****
Excode   Job#   Description      EXTRAS      Qty      Price      Total
*****
FRT      1   UPS-FAUCET                1.00     15.21     15.21

```

```

Parts Total:      75.97
Labour Total:     312.00
Sublet Total:      0.00
Extras Total:     15.21

```

>>>> Claim Total: 403.18

Customer Signature: _____

Date: _____