



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70358

CUSTOMER WORK ORDER

WO #: 70358

Customer: 1000 - BASDEN'S
AMERICAN RV -

Tag:

Author: PH

Location: 0428 SEE IF THIS CAN BE
CLOSED

Stock #: 11265

Stock Desc: 2023 TT FOREST RIVER

CHEROKEE WOLF PUP 16CW

Chassis #: 5ZT2CKEC3PY029338

Serial #: 5ZT2CKEC3PY029338

Mileage: 0

Licence:

Invoice #:

Date In: 13 APR 23

Promised:

Date Sched:

Completed: 28 APR 23

Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: PDIED NEW TRAVEL TRAILER WAITING ON PARTS PARKED IN PARTS WAITING

CORRECTION: PDIED NEW TRAVEL TRAILER WAITING ON PARTS PARKED IN PARTS WAITING

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C

Parts

Part #	Description	Qty	Price	Total
13-1320	PW HAPS FREE SELF-LEVELING DICOR	1.00	N/C	N/C
40325	40325 2-PK BUMPER CAP W/INSECT SCREEN	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: WATER HEATER DOOR NOT LATCHING

CAUSE: WATER HEATER DOOR NOT LATCHING AS PLASTIC LATCH IS BROKE OFF NEED NEW
LATCH

CORRECTION: WATER HEATER DOOR NOT LATCHING AS PLASTIC LATCH IS BROKE OFF NEED
NEW LATCH

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	30.40
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	1.60



Customer #:
1000



**Parts**

Part #	Description	Qty	Price	Total
F100345503	WATER HEATER, 15" X 15" HINGED DOOR ONLY - BLACK, FOR FURRION 2.4 GPM (BULK RACK 2 SHELF 2 SIDE B)	1.00	23.24	23.24
90M13170A	GEOCEL 2300 CLEAR SEALANT	1.00	7.48	7.48

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-DOOR	1.00	15.82	15.82

Subtotal for Job #1: 78.54

Job #2 - Warranty

COMPLAINT: FRONT COMPARTMENT DOOR WONT OPEN

CAUSE: FRONT COMPARTMENT DOOR WONT OPEN AS LATCH WAS SCREWED ON WAY TO TIGHT CAUSING IT NOT TO MOVE. LOOSENEED SCREW AND NUT TO ALLW IT TO LOCK AND UNLOCK PROPPERLEY

CORRECTION: FRONT COMPARTMENT DOOR WONT OPEN AS LATCH WAS SCREWED ON WAY TO TIGHT CAUSING IT NOT TO MOVE. LOOSENEED SCREW AND NUT TO ALLW IT TO LOCK AND UNLOCK PROPPERLEY

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	16.00

Subtotal for Job #2: 16.00

Job #3 - Internal

COMPLAINT: BATHROOM SEAM TAPE LOOSE

CAUSE: BATHROOM SEAM TAPE LOSE.REINSTALLED WITH ADHSEIVE

CORRECTION: BATHROOM SEAM TAPE LOSE.REINSTALLED WITH ADHSEIVE

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: SCUFF MARK ON METAL NEAR AWNING ARM

CAUSE: SCUFF MARKS ON METAL AROUND AWNING WHERE THEY PUT AWNING ARM ON. TOOK CLEANER AND CLEANED SCUFF MARKS UP. UPON FURTHER INSPECTION FOUND METAL HAS A SCRATCH IN IT. NEEDS NEW METAL

CORRECTION: SCUFF MARKS ON METAL AROUND AWNING WHERE THEY PUT AWNING ARM ON. TOOK CLEANER AND CLEANED SCUFF MARKS UP. UPON FURTHER INSPECTION FOUND METAL HAS A SCRATCH IN IT. NEEDS NEW METAL

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	640.00
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	0.00

Parts

Part #	Description	Qty	Price	Total
F100341155	SIDING, 12" X LENGTH - POLAR WHITE W/ TUFF COAT, S-LOK / 2023 (SOLD PER/FT. - 30' MAX)	12.00	4.60	55.20



**Other Services**

Code	Description	Qty	Price	Total
FRT	UPS FREIGHT - METAL	1.00	191.79	191.79
Subtotal for Job #4:				886.99

Job #5 - Warranty

COMPLAINT: TORN SPOT ON THE ENTRY HANDLE

CAUSE: TORN SPOT IN ENTRY HANDLE NEEDS NEW ONE

CORRECTION: TORN SPOT IN ENTRY HANDLE NEEDS NEW ONE

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	32.00
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	0.00

Parts

Part #	Description	Qty	Price	Total
90M39173A	GRAB HANDLE, FOLD AWAY, SHORT, BLACK MM FLOOR	1.00	15.86	15.86

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-HANDLE	1.00	12.37	12.37
Subtotal for Job #5:				60.23

Parts Total: 101.78
Labour Total: 720.00
Sublet Total: 0.00
Extras Total: 219.98
WORK ORDER TOTAL: 1,041.76

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 28 Apr 2023

