



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70452
Promised Date:
26 APR 23

CUSTOMER WORK ORDER

WO #: 70452 (Appointment Date: 22 APR 2023 - Time: 09:00am)

Customer: 52956 - KRACK, RAY W. -
812-454-9658

Tag:

Author: BH

Location: 0427 CHECK STATUS WITH
SAR

Stock #: 10821

Stock Desc: 2022 TT FOREST RIVER

CHEROKEE 264DBH

Chassis #: 4X4TCKB29NX157405

Serial #: 4X4TCKB29NX157405

Mileage:

Licence:

Invoice #: 390223

Date In: 22 APR 23

Promised: 29 APR 23

Date Sched:

Completed: 26 APR 23

Warr. Date: 27 AUG 22

Job #SUMMER - External

COMPLAINT: DE-WINTERIZE UNIT

CORRECTION: FILLED FRESH TANK TO 1/3 FULL TO FLUSH OUT THE SHOWER, OUTSIDE SHOWER, TOILET, KITCHEN SINK, BATHROOM SINK, OUTSIDE KITCHEN. WHILE FLUSHING THESE CAME ARCOSS PINK IN THE LINES. THE FRESH TANK HAD ANTIFREEZE PUT IN IT. HAD TO FLUSH OUT THE FRESH TANK AND WATER HEATER TILL HAD CLEAR WATER. FILLED FRESH TANK 80% FULL TO FLUSH BOTH TANK AND WATER HEATER. THEN FLUSHED OUT ALL SHOWER, OUTSIDE SHOWER, TOILET, OUTSIDE KITCHEN, KITCHEN SINK, BATHROOM SINK TILL THERE WAS CLEAR WATER. SYSTEM WAS NOT 100% WINTERIZED THAT IS WHY THE KITCHEN SINK WAS BROKEN. RAN AIR THRU LINES TO CHECK FOR LEAKS BEFORE DEWINTERIZE. NO LEAKS WERE FOUND SUCH AS BEHIND THE WATER HEATER, WATER PUMP, AND FAUCETS. THE VALVES ON WATER HEATER AND WATER PUMP WERE NEVER TURNED FOR WINTERIZATION. DRAINED BLACK AND GREY TANKS.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #SUMMER: 0.00

Job #2 - Warranty

COMPLAINT: REPLACE KITCHEN SINK FAUCET IT IS BROKEN

CORRECTION: TOOK PICTURES OF BROKEN FAUCET. PUT IN PO FOR NEW KITCHEN FAUCET. RECIEVED NEW KITCHEN FAUCET. UNBOXED NEW FAUCET. DISASSEMBLED BROKEN FAUCET AND WATER LINES. INSTALLED NEW FAUCET. WILL TEST FAUCET DURING DEWINTERIZATION. NO LEAKS WERE FOUND AFTER REPLACING FAUCET.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	80.00

Parts

Part #	Description	Qty	Price	Total
6615	COILED PULL-DOWN FAUCET - BLACK MATTE	1.00	146.51	146.51

Subtotal for Job #2: 226.51



Customer #:
52956

W/O: 70452
Promised Date:
29 APR 23



Customer #:
52956



Job #3 - External
COMPLAINT: FILL LP

CORRECTION: REMOVED COVER TO LP TANKS THE DISCONNECTED THE LP HOSES FROM THE LP TANKS. PUT TANKS ON CART TO FILL OUTSIDE WITH LP. FILLED ONLY 1-20 LB TANK OTHER TANK WAS FULL. PUT TANKS BACK IN PLACE AND TIGHTENED DOWN THEN CONNECTED THE LP HOSES.

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		SAR	N/C
Other Services				
Code	Description	Qty	Price	Total
LP20	20 LB. LP CYLINDER	1.00	N/C	N/C
Subtotal for Job #3:				0.00

Job #LIPPERT - Warranty
COMPLAINT: #22-434 LIPPERT AWNING RECALL (INSPECTION)

CORRECTION: GOT A SCISSOR LIFT TO CHECK THE LENGTH OF THE AWNING. RAN AWNING OUT ABOUT 6 INCHES. TOOK PICTURES OF AWNING. ON THE FRONT SIDE OF AWNING HAS A SMALL TEAR JUST ABOVE THE LED LIGHTS. NO OTHER DAMAGE WAS FOUND WHILE INSPECTING AWNING. RETRACTED THE AWNING WHEN DONE WITH INSPECTION.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	48.00
Subtotal for Job #LIPPERT:			48.00

Parts Total:	146.51
Labour Total:	128.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	274.51

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 26 Apr 2023

