



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70457
Promised Date:
20 APR 23

CUSTOMER WORK ORDER

WO #: 70457 (Appointment Date: 22 APR 2023 - Time: 10:00am)

Customer: 52332 - HOPPEN, JUSTIN B. - Stock #: 10948

812-598-2243

Tag:

Author: PH

Location: 0510 CHECK PARTS

Stock Desc: (10948) 2022 KEYSTONE

SPRINGDALE 260BH

Chassis #: 4YDTSGL23N3101906

Serial #: 4YDTSGL23N3101906

Mileage:

Licence:

Invoice #:

Date In: 22 APR 23

Promised: 29 APR 23

Date Sched:

Completed: 05 MAY 23

Warr. Date: 04 MAR 22

Job #1 - Warranty

COMPLAINT: AC NOT BLOWING COLD

CAUSE: A/C ONLY PULLING 6 AMPS AT COMPRESSOR. NEEDS REPLACED.

CORRECTION: REMOVED INSIDE SHROUD AND HARDWARE, REMOVED WIRES AND FREEZE SENSOR. GOT FORK TRUCK AND REMOVED A.C UNIT. SET NEW A/C ON ROOF. POSITIONED AROUND CUT OUT. INSTALLED HARDWARE, CONTROLL BOX, FREEZE SENSOR, MOUNTING BOLTS. INSIDE SHROUD. RAN A/C FOR TESTING. CLEANED UP MESS. PARKED UNIT.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	70.40
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	169.60

Parts

Part #	Description	Qty	Price	Total
7019	A/C - 13.5 BTU - GE RVAC - 3 Fan Spe	1.00	683.91	683.91

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00
FRT	FREIGHT-A/C	1.00	172.38	172.38

Subtotal for Job #1: 1,096.29

Job #22-423 - Warranty

COMPLAINT: RECALL 22-423 KEYSTONE SOLAR CONTROLLER WIRING

CORRECTION: updated firmware on solar controller. sent pics to ben

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	48.00

Subtotal for Job #22-423: 48.00



Customer #: 52332
HOPPEN, JUSTIN B.

W/O: 70457
Promised Date: 29 APR 23

Parts Total:	683.91
Labour Total:	288.00
Sublet Total:	0.00
Extras Total:	172.38
WORK ORDER TOTAL:	1,144.29

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 05 May 2023

Customer Work
Order



Customer #: 52332
HOPPEN, JUSTIN B.

