



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70482
Promised Date:
20 JUN 23

CUSTOMER WORK ORDER

WO #: 70482

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 0701 CHECK PREAUTH

Stock #: 11079
Stock Desc: 2023 TT FOREST RIVER
CHEROKEE GREY WOLF 20RDSE
Chassis #: 5ZT2CKJB5PF004529
Serial #: 5ZT2CKJB5PF004529
Mileage: 0
Licence:

Invoice #:
Date In: 25 APR 23
Promised: 30 JUN 23
Date Sched:
Completed: 28 JUN 23
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CORRECTION: INSPECTED TRAILER AND ALL APPLIANCES

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JP	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JP	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JP	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	4.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: WATER LEAKING FROM GREY TANK

CAUSE: water is leaking at fitting coming out of tank

CORRECTION: water is leaking at fitting coming out of tank, jack up left side of unit, and set on jack stands, remove left front tire and let axle drop to have room for tech to get to leak, loosen band and cut drain pipe and try to separate from tank, line will not move, remove screws from underbelly, end screws of underbelly was shot from top before floor was put on, underbelly is around tanks, cut underbelly and pull down to find parts #s on tank put together and turn up for tanks fittings and line (3in to 1 1/2in) put tire back on and unjack

BRING BACK IN GET PARTS FROM PARTS DEPT. OPEN CABINETS REMOVING DRAWS AND ACCESS PANELS ON KITCHEN SINK DRAIN LINE, REMOVE WALL BOARD IN HALL TO GAIN ACCESS TO DRAIN LINES FOR SHOWER AND BATHROOM SINK, CUT DRAIN LINES, CUT TANK DRAIN LINE, REMOVE MONITOR WIRES, REMOVE TANK SUPPORT, AND PULL TANK OUT, SET NEW TANK NEXT TO OLD TANK AND MARK FOR HOLE LOCATIONS, DRILL HOLES AND INSERT TANK GRAMMETS IN TANK, CUT LINES TO FIT TANK IN PLACE, INSTALL SUPPORT, RUN LINES FOR 2 SINKS AND SHOWER TO TANK AND FASEN UP, CONNET WIRE FROM MONITORS AND TEST, CONNET UP DRAIN LINE, WATER TEST FOR LEAKS, FILL TANK WITH WATER AND LET SIT, PUT KITCHEN CABINET BACK TOGETHER PUT WALL BACK TOGETHER, DRAIN TANK, PUT UNDERBELLY BACK UP, SEAL UNDER BELLY WITH TAPE AND FOAM SEALER, CLEAN UP BUILD TRASH OUT OF UNIT CLOSE UP UNIT AND PUT OUT ON SALES LOT

Customer #: 1000
BASDEN'S AMERICAN RV,





Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	80.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	400.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	160.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	160.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00

Parts

Part #	Description	Qty	Price	Total
3673	1.5" FERNCO COUPLER	4.00	9.34	37.36
89-8067	90 STREET ELBOW 1 1/2"	1.00	3.58	3.58
69-9244	1.5" ABS PIPE	1.00	37.85	37.85
60P05751A	ELBOW, 1 1/2" 90 DEG. LONGSWEEP	1.00	1.93	1.93
	STRE			
20X51398A	TANK, 59" X 28" X 8" HOLDING TANK	1.00	110.76	110.76
	LH			
60P12642A	TANK REDUCER, VALTERA T1041-1 3"	1.00	1.16	1.16
	SPG			
11-0995	1-1/2" TANK GROMMETS	2.00	5.19	10.38
11-1119	1-1/2" BEND-1/8	1.00	2.25	2.25
100815	Fitting - ABS - Str Elbow - 1 1/2" -	1.00	0.66	0.66

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT	1.00	133.03	133.03

Subtotal for Job #1: 1,138.96

Parts Total: 205.93
 Labour Total: 800.00
 Sublet Total: 0.00
 Extras Total: 133.03
WORK ORDER TOTAL: 1,138.96

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 28 Jun 2023

