



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70511
Promised Date:
26 MAY 23

CUSTOMER WORK ORDER

WO #: 70511

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 0525 CHECK PREAUTH

Stock #: 10745
Stock Desc: 2023 TT COACHMEN
CATALINA 283RKSLE
Chassis #: 5ZT2CATB5PX028914
Serial #: 5ZT2CATB5PX028914
Mileage: 0
Licence:

Invoice #:
Date In: 27 APR 23
Promised: 26 MAY 23
Date Sched:
Completed: 23 MAY 23
Warr. Date:

Job #PDINTT - Internal

PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: FRESH TANK NOT REGISTERING ON MONITOR

CAUSE: FRESH TANK NOT REGISTERING ON MONITOR.

CORRECTION: Checked all wires to fresh tank. Found ground wire had been cut off. Pliced wires back together. Monitor panel now reading.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	51.20
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	28.80

Subtotal for Job #1: 80.00

Job #2 - Warranty

COMPLAINT: WATER NOT FLOWING TO BATHROOM & OUTSIDE SHOWER

CAUSE: WATER NOT FLOWING TO BATHROOM AND OUTSIDE SHOWER.

CORRECTION: Underbelly had been cut and taped at factory. Pulled tape off and found water line bent over and pinched not letting water get to front bathroom. Cut Clamps off at tees next to low point drains. Cut off flattened area on both hoses. Installed 90 deg fittings to eliminate flattened hose sections. Crimped all hose clamps. Added water to fresh water tank and checked all fitting for leaks. All OK.



Customer #: 1000
BASDEN'S AMERICAN RV,

Resealed holes that were cut in underbelly with underbelly tape.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	48.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	56.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	80.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	32.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	144.00

Parts

Part #	Description	Qty	Price	Total
51139	1/2" BRASS PEX ELBOW	2.00	2.22	4.44

Subtotal for Job #2: 364.44

Job #3 - Warranty

COMPLAINT: FRESH WATER FILL HOSE LEAKING AT TANK

CAUSE: FRESH WATER FILL HOSE LEAKING AT TANK.

CORRECTION: Fill hose is not up on tank fitting to seal. Loosened hose clamp and removed fill hose from tank. Added silicone sealed to inside of hose. Pushed hose all the way onto tank fitting. Tightened hose clamp. Checked for water leak. OK.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	80.00

Subtotal for Job #3: 80.00

Job #4 - Warranty

COMPLAINT: TEST TV WILL NOT PICK UP CHANNELS

CAUSE: TEST TV WILL NOT PICK UP CHANNELS.

CORRECTION: Checked coax from antenna to booster. It was connected to cable inlet on booster instead of to antenna on booster. Coax connector on antenna cable was shorted. Installed new cable end on antenna coax. Checked TV at all outlets.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	240.00

Subtotal for Job #4: 240.00

Job #5 - Warranty

COMPLAINT: SHADE ON DOOR SIDE LIVING ROOM WILL NOT GO DOWN

CAUSE: SHADE ON DOOR SIDE LIVING ROOM WILL NOT GO DOWN.

CORRECTION: Checked operation of shade. right side string has a knot in it. Only allows shade to pull down about half way. Removed bottom screw anchor. Picked at knot until it came loose and untied. Remounted bottom screw anchor. Checked operation of shade. Shade now pulls down and pushes back up.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	15.00

Subtotal for Job #5: 15.00

W/O: 70511
Promised Date: 26 MAY 23



Customer #: 1000
BASDEN'S AMERICAN RV,



W/O: 70511
Promised Date: 26 MAY 23

Parts Total:	4.44
Labour Total:	775.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	779.44

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 23 May 2023



Customer #: 1000
BASDEN'S AMERICAN RV,

