

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 70529
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 50350 - DAVID FISCHER
Address: 5512 RYAN LN

47712

Phone: 8127745016

Stock Number: 2022 CATALINA 5ZT2CAZB8NX026806

VIN: 5ZT2CAZB8NX026806 HIN:

SER#: 5ZT2CAZB8NX026806

Mileage:

Work Order Comp: 26 MAY 23

Auth. No:

Dealer #:

Warr. Date:

Work Order Date: 29 APR 23

Inv #: 391668

WO #	Job #	Description	JOB INFORMATION
70529	1	CUSTOMER NOTICES SEVERAL AREAS INSIDE WHERE TRAILER IS LEAKING. UNIT WAS STORED INDOORS THRU WINTER. NOW THAT THAT IT IS ON A CAMPSITE HE HAS NOTICED THE LEAKS. LIVING SLIDE LEAKS AT BOTH LOWER CORNERS. YOU CAN SEE WHERE THE CABINET IS COMING APART. BRING IN UNIT, INSPECT ROOF AND FOUND A SMALL HOLE IN RUBBER ON FRONT LEFT CORNER, FRONT CORNER MOLDING SEALER IS PULLING AWAY, SLIDE OUTS HAVE SEALING TAPE PULLING LOOSE, WALL BOARD IN BEDROOM CLOSET IS WATER DAMAGE, CABNET OVER BED SHOWS WATER AT TOP SEAM, ROOF NEEDS A PATCH OVER HOLE, AND NEEDS RESEALING REMOVED SHELF IN CLOSET. REMOVE TRIM ON SIDES. CUT OUT DAMAGED WALL BOARD. CUT AND INSTALL NEW WALL BOARD. PUT ON NEW TRIM AND SILICONED. PUT BACK SHELF. REMOVE CLOTHS AND GAMES IN CLOSET. REMOVE LIGHT AND CLOTHS BAR. REMOVE DAMAGED WALL PANEL. CUT AND INSTALL NEW WALL PANEL. PUT ON NEW TRIM AND SILICONED. PUT LIGHT BACK AND PUT BAR BACK.. CLEANED UP.	
70529	2	THERE IS A LEAK AT THE RIGHT SIDE OF THE SHOWER WHEN USING. SHOWER BASE IS NOT SEALED ALL THE WAY AROUND DOOR FRAME, NEEDS TO BE RESEALED RESEAL AROUND SHOWER DOOR FRAME AT BASE	
70529	4	THE OUTDOOR KITCHEN DOOR IS CROOKED AND DOES NOT SHUT PROPERLY. OUT SIDE KITCHEN DOOR FRAME IS NOT START AND DOOR IS HITTING FRAME ON BOTTOM BACK CORNER, NEEDS TO BE PULLED AND FRAME TRIMED AND RESET TOOK SCREWS OUT ON THE LEFT SIDE AND PUT A CLAMP ON IT AND	

Claim : 70529

 WO # Job # Description JOB INFORMATION

 BROUGHT IT OVER ENOUGH TO CLOSE RIGHT.

70529 6 CUSTOMER HAS TO SLAM MAIN DOOR HARD TO GET IT TO CATCH. NEEDS
 SCREEN REPLACED AND A DOG GUARD ADDED IF IT IS LIPPERT
 DOOR IS A DEXTER DOOR, NEEDS SCREEN, DOOR FRAME HAS A BOW IN ON
 LATCH SIDE
 REMOVED SCREEN DOOR FROM UNIT. GOT NEW SCREEN FROM THE BACK ROOM.
 INSTALLED NEW SCREEN TO DOOR. REHUNG DOOR BACK ON UNIT.

70529 7 THE CABINET DOORS BELOW THE TV IN BUNKROOM KEEP FALLING OFF
 CABNET DOOR NEEDS TO BE GLUED UP OR REPLACED
 REMOVE CABINET DOOR AND TOOK HARDWARE OFF AND PUT IT ON NEW DOOR.
 INSTALLED NEW DOOR

 Part No Job# Description PARTS Qty Price Total

 F100130689 1 SEAM TAPE - PER FT. 25.00 0.15 3.75
 F100130672 1 7/8" BATTEN VIPER TRUFFLE 2.00 1.86 3.72
 F100283256 1 DOOR, FPSQ CHILI TEAK 15.75 X 24. 1.00 31.10 31.10
 F100130702 1 TAPE, SEAM VINYL 1" - 150' ROLL - 25.00 0.15 3.75
 F100130671 1 BATTEN, #195 GABLE LATTE, 7/8" X 2.00 1.96 3.92
 F100410635 1 4X7 WALL GABLE 1.00 43.67 43.67

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 160.00 0.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 160.00 0.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 1.50 160.00 240.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 160.00 0.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 2.50 160.00 400.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 1.50 160.00 240.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 2.50 160.00 400.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.30 160.00 48.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.00 160.00 0.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.00 160.00 0.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.00 160.00 0.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 1.00 160.00 160.00
 Z990 6 MISC LABOUR CODE (EXTERNAL) 1.00 160.00 160.00
 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.50 160.00 80.00
 Z990 7 MISC LABOUR CODE (EXTERNAL) 0.00 160.00 0.00
 Z990 7 MISC LABOUR CODE (EXTERNAL) 0.00 160.00 0.00
 Z990 7 MISC LABOUR CODE (EXTERNAL) 0.50 160.00 80.00

 Excode Job# Description EXTRAS Qty Price Total

 FRT 1 FREIGHT & CRATE - BOARD, TRIM, TAPE 0.00 0.00 0.00

Claim : 70529

 Excode Job# Description EXTRAS Qty Price Total

Parts Total: 89.91
 Labour Total: 1,808.00
 Sublet Total: 0.00
 Extras Total: 0.00
 >>>> Claim Total: 1,897.91

Customer Signature: _____

Date: _____