



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70535

CUSTOMER WORK ORDER

WO #: 70535

Customer: 52193 - SPIEHLER, MARK -
812-319-2757

Tag:

Author: PH

Location: 0505 CHECK PREAUTH

Stock #: 11156

Stock Desc: 2022 TT KEYSTONE
COUGAR HALF-TON 29BHS

Chassis #: 4YDTCGP21NV507131

Serial #: 4YDTCGP21NV507131

Mileage:

Licence:

Invoice #:

Date In: 01 MAY 23

Promised:

Date Sched:

Completed: 03 MAY 23

Warr. Date: 28 FEB 23

Job #1 - Warranty

COMPLAINT: SHELVES IN PANTRY IS FALLING DOWN AND BASEBOARD AT BOTTOM IS CAVED IN

CORRECTION: REMOVE STAPLES AND PUT BACK FRONT TRIM AND STAPLE IT AND NAIL IT. FILE HOLES

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BB	32.00
Subtotal for Job #1:			32.00

Job #2 - Internal

COMPLAINT: TOILET SEAT IS FALLING APART

CORRECTION: TIGHTEN SEAT AND TOLD PETE THEY MIGHT NEED A HEAVIER SEAT.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BB	N/C
Subtotal for Job #2:			0.00

Job #3 - Internal

COMPLAINT: AWNING HAS A LEAK AT THE CAMPER SEAM BETWEEN THE SPEAKERS.

CORRECTION: SILICONED GUTTER ABOVE SPEAKERS

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BB	N/C
Subtotal for Job #3:			0.00

Job #4 - Warranty

COMPLAINT: TV HAS PICTURE ISSUE. SEE BEN, HE IS SENDING PICTURES IN

CORRECTION: BEN SAID TAKE PICS OF MODEL NUMBER. AND HE WOULD TAKE CARE OF IT.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BB	0.00
Z990	MISCELLANEOUS REPAIR	BB	0.00
Z990	MISCELLANEOUS REPAIR	BB	48.00

Parts

Customer #: 52193
SPIEHLER, MARK



Part #
6458644

Description
Toshiba - 50" Class C350 Series LED 4K
UHD Smart Fire TV

Qty
1.00

Price
300.00

Total
300.00

Subtotal for Job #4: 348.00

W/O: 70535

Parts Total: 300.00
Labour Total: 80.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 380.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 03 May 2023



Customer #: 52193
SPEHLER, MARK

