

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 70542
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER

Customer: 53184 - DOUG DIEDRICH

Address: 4515 MARBLE DR

NEWBURGH, IN

47630

Phone: 812-305-6870

Stock Number: 2022 NO BOUNDRIES 20.4

VIN:

HIN:

SER#: 4X4TRPV28NR207772

Mileage:

Work Order Comp: 11 MAY 23

Auth. No:

Dealer #:

Warr. Date:

Work Order Date: 01 MAY 23

Inv #: 390964

WO # Job # Description JOB INFORMATION

70542 1 CUSTOMER CAMPED THIS PAST WEEKEND AND DISCOVERED THAT WHEN THEY
USE HOT WATER, WATER LEAKS FROM UNDER THE KITCHEN SINK IN THE
AREA OF THE WATER HEATER. WATER RUNS OUT INTO THE FLOOR AT THE
END OF THE SINK/BAR AREA. THIS HAPPENS WHEN CUSTOMER USES HOT
WATER AT THE KITCHEN SINK AND THE SHOWER AS WELL.
water leak when using hot water.
pulled unit in shop. hooked up to shore power. turned on water
heater. added some water to fresh tank. ***water pump was still
in bypass mode.*** after letting water heater warm up i turned
the water pump on to pressurize system. removed panel under sink.
noticed water on and around both hot and cold fittings going into
the back of the water heater. tightened up both fittings. removed
panel under shower to make sure nothing was leaking. let system
heat up again and pressurize. no more leaks present. cleaned up
mess.parked unit.

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 1 MISC LABOUR CODE (EXTERNAL) 1.00 160.00 160.00

Excode Job# Description EXTRAS Qty Price Total

SS 1 SHOP SUPPLIES 1.00 0.00 0.00

Parts Total: 0.00
Labour Total: 160.00
Sublet Total: 0.00
Extras Total: 0.00

>>>> Claim Total: 160.00

Customer Signature: _____

Date: _____

Claim : 70542

Excode	Job#	Description	EXTRAS	Qty	Price	Total
