

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 70548
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 52977 - TRAVIS R. LAWYER
Address: 104 S COUNTY RD 1150 W FRENCH LICK, IN

47432

Phone: 812-827-1920

Stock Number: 11084 - 2022 SABRE 37FLH 5ZT3SR2B3N6110618

VIN: 5ZT3SR2B3N6110618 HIN: SER#: 5ZT3SR2B3N6110618

Mileage: 0

Work Order Comp: 26 JUN 23

Auth. No:

Dealer #:

Warr. Date: 27 AUG 22

Work Order Date: 02 MAY 23

Inv #: 393175

WO #	Job #	Description	JOB INFORMATION
------	-------	-------------	-----------------

70548	1	CHECK FRIDGE NOT COOLING AND FREEZING UP Fridge freezing up Open slide rooms so So fridge could fit While removing bad fridge and installing new fridge. Removed table and chairs and the mounts that hold the fridge in. Pulled fridge out of cabinets and disconnected the power to the back of the fridge. Laid cardboard on floor to set fridge on. Had to remove the window in the slide room to slide the fridge out with the Forktruck. Put new fridge on Forktruck and brought up into the window. Put window back in slide room. Move new fridge to cabinet area and tied up wires and put into place of cabinet. Put dining table and chairs back in place and screw the dining table back to the floor. Cleaned up the mess of cardboard that we used to run the fridge across to protect the floors. Applied new silicone at the top of the window to capsule since I had to cut the old silicone to remove the window. Put thermometers inside fridge and will let sit to check temperature later. How to remove the buttons from the old fridge and restick to the new fridge with new? Double sided tape so the doors will stay shut during travel. Take pictures of progress. We'll check the fridge temp the next day. Couldn't get old fridge to duplicate as customers stated this customer needs fridge back ASAP. Customer does live in camper full time. After new fridge was installed set fridge to smart settings, Which gave me a setting in the fridge of forty degrees and the freezer negative zero which bottles of antifreeze were accurate with Thermometers.	
-------	---	---	--

Claim : 70548

 WO # Job # Description JOB INFORMATION

 Part No Job# Description PARTS Qty Price Total

 F100300311 1 REFRIGERATOR, EVERCHILL 16.2 CUFT 1.00 1802.63 1802.63

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 1 MISC LABOUR CODE (EXTERNAL) 2.00 160.00 320.00

 Excode Job# Description EXTRAS Qty Price Total

 FRT 1 FREIGHT-REFER 1.00 113.88 113.88

Parts Total: 1,802.63
 Labour Total: 320.00
 Sublet Total: 0.00
 Extras Total: 113.88

>>>> Claim Total: 2,236.51

Customer Signature: _____

Date: _____