

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 70575
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 53613 - LOUIS D. BRUCE
Address: 3120 MESKER PARK DR EVANSVILLE, IN

47720

Phone: 812-459-9796

Stock Number: 11020 - 2023 CATALINA SUMMIT SERIES 164BH 5ZT2CAEC3PK005473

VIN: 5ZT2CAEC3PK005473 HIN: SER#: 5ZT2CAEC3PK005473

Mileage: 0 Work Order Comp: 17 MAY 23

Auth. No: Dealer #:

Warr. Date: 12 MAY 23 Work Order Date: 06 MAY 23 Inv #: 391206

WO # Job # Description JOB INFORMATION

70575 1 LIGHTS BLOW FUSE WHEN WHEN 7 WAY IS HOOKED UP AND TESTED
LIGHTS BLOW FUSE WHEN 7 WAY IS HOOKED UP
When tail lights care turned "ON" with test box the fuse blows.
Removed junction box cover under front frame. Checked all wire
connections. All connections good and correct. Removed both
rear tail lights. Checked connections. All good and correct.
Removed all rear clearance lights. Checked connections All good
and correct. Still blowing fuse in test box. Cut all lights
loose from wiring. Started checking wires from light to light.
Found that positive wire from roadside left clearance to next one
over was shorted. Fished a new positive wire between these two
lights. Taped off old wire at both ends. Connected lights
together. Lights now work. Remounted all rear lights and
resealed. Checked lights again after reassembly. All working
ok.

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 1 MISC LABOUR CODE (EXTERNAL) 1.50 160.00 240.00
Z990 1 MISC LABOUR CODE (EXTERNAL) 0.50 160.00 80.00
Z990 1 MISC LABOUR CODE (EXTERNAL) 1.00 160.00 160.00

Parts Total: 0.00
Labour Total: 480.00
Sublet Total: 0.00
Extras Total: 0.00

>>>> Claim Total: 480.00