

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
BASDEN RV CENTER INC
DBA AMERICAN RV CENTER
600 E BASELINE ROAD
EVANSVILLE, IN 47725
USA

Labor rate: \$160.00

OWNER INFORMATION

LOUIS D BRUCE
3120 MESKER PARK DR
Evansville, IN 47720
USA

CLAIM STATUS Authorized
CLAIM 1534162
CLAIM ORIGIN WEB
ORIGINAL CLAIM ID
VIN 5ZT2CAEC3PK005473
CHASSIS VIN
MILEAGE 0
SITE/WAREHOUSE 203 / 203
ITEM # BCAT164BH
DEALER RO # 70575
CLAIM START DATE 05/16/2023
CLAIM END DATE 01/01/1900

Retail Date of Purchase 05/12/2023

WARRANTY EXPIRATION DATE 05/12/2024

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description
	42-622-11-24-001253	Exterior 12 Volt Wiring - Cargo Electrical/12 Volt Exterior/Electrical/Repair
Complaint, Cause, Correction		
Original Note : bhoffman@americanrvcenter.com, 2023-05-16 14:55:12 :: LIGHTS BLOW FUSE WHEN WHEN 7 WAY IS HOOKED UP AND TESTED LIGHTS BLOW FUSE WHEN 7 WAY IS HOOKED UP When tail lights care turned "ON" with test box the fuse blows. Removed junction box cover under front frame. Checked all wire connections. All connections good and correct. Removed both rear tail lights. Checked connections. All good and correct. Removed all rear clearance lights. Checked connections All good and correct. Still blowing fuse in test box. Cut all lights loose from wiring. Started checking wires from light to light. Found that positive wire from roadside left clearance to next one over was shorted. Fished a new positive wire between these two lights. Taped off old wire at both ends. Connected lights together. Lights now work. Remounted all rear lights and resealed. Checked lights again after reassembly. All working ok.		
	Model #	Dlr Sub Hrs 4.00
	Serial #	Appr Hrs 3.00
		Sub Labor Amt \$640.00
		Appr Labor Amt \$480.00
Notes		
EXCESSIVE AMOUNT REQUESTED CHANGED TO SIMILAR REPAIR TIME		

Submitted	Labor Amt	\$640.00	Approved	Labor Amt	\$480.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$640.00		Total	\$480.00

DEALER DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.