



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70596

CUSTOMER WORK ORDER

WO #: 70596

Customer: 11817 - MEYER, BRYAN E. -
812-664-5566

Tag:

Author: BH

Location: 0515 CHECK PREAUTH

Stock #: 10468

Stock Desc: 2022 TT COACHMEN

SPIRIT 1943RB

Chassis #: 5ZT2SBHB4NS044095

Serial #: 5ZT2SBHB4NS044095

Mileage:

Licence:

Invoice #:

Date In: 08 MAY 23

Promised:

Date Sched:

Completed: 08 MAY 23

Warr. Date: 26 MAY 22

Job #1 - Warranty

COMPLAINT: CHECK VALVE IS LEAKING WHEN FLUSHING THE BLACK TANK

CAUSE:

FOUND VALVE IS LEAKING

CORRECTION: NEED TO REPLACE THE VALVE

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	48.00

Parts

Part #	Description	Qty	Price	Total
282770	94239 VACUUM BREAKER/CHECK VALVE	1.00	21.25	21.25

Subtotal for Job #1: 69.25

Parts Total: 21.25
Labour Total: 48.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 69.25

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 08 May 2023



Customer #: 11817
MEYER, BRYAN E.