

e-Authorization

5/23/20
12:10:09 PM

3- Authorization number PA03439589	Reference no: 70667	Status: Approved	Approved by anglr	Approved date 5/17/2023
Authorizing Name	Address	VIN	Retail sold on	

34	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	4YDTCGK26NL508990	3/17/2023				
du Root e operation of	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	2205506B Attic Vent - Roof	0.00	1.00	0.30		1	0.30	Complaint:ROOF LEAK ON A CEILING MIGHT BE WHERE THE SOLAR PANEL PLUG IS Cause:VENT CAP BUSTED Correction:FOUND VENT CAP CRACKED. TOOK PICS. REMOVED CAP AND CLEANED OFF DICOR. PUT NEW CAP ON AND PUT ALPA DICOR ON IT.
2	4127506B Refrigerator - Nor	0.00	0.30	0.30		1	0.50	KRV – Labor time approved in accordance with Keystone RV's flat rate manual. VCB: Vendor Charge Back item. (This is a Keystone RV internal notation only) Complaint:THE FREEZER DOOR DOES NOT LATCH LIKE THE REFRIGERATOR DOOR DOES. CUSTOMER THINKS THAT A PIN IS POSSIBLY BROKEN. Cause:FOUND FREEZER HANDLE BROKEN Correction:REPLACE FREEZER DOOR HANDLE VCB: Vendor Charge Back item. (This is a Keystone RV internal notation only) KRV - need model and serial # from refer with claim
3- Authorization number PA03439589				0.60				

For paper claims ~~only~~, use one pre-authorization number per warranty claim for
multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the