

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 70673
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 52345 - DENNIS R. TURPIN, II
Address: 2622 E BRENTWOOD DR PRINCETON, IN

47670

Phone: 812-779-7607

Stock Number: 11070 - 2022 SABRE 36BHQ 5ZT3SR1B6N6109674

VIN: 5ZT3SR1B6N6109674 HIN: SER#: 5ZT3SR1B6N6109674

Mileage: 0 Work Order Comp: 23 MAY 23

Auth. No: Dealer #:

Warr. Date: 26 MAR 22 Work Order Date: 17 MAY 23 Inv #: 391475

WO # Job # Description JOB INFORMATION

70673 2 SLIDEROOM IS STUCK
slide room will not move in or out.
went underneath and opened under belly. motor and wiring look
good. removed top and bottom set screws and removed motor from
slide assembly. took motor to work bench and removed cover plate.
clutch and gears all look good. noticed that after we removed the
motor the slide room assembly moved. removed slide ram. slide ram
looks good. reinstalled motor on ram and hooked up to a battery.
lubricated ram and ran on and out several times on the ground.
went to re installed motor and ram. when trying to install the
motor back the way it was before, i realizewd that the motor is
hitting on the surrounding frame. override doesnt line up with
hole in frame. MOTOR ISNT ORIENTATED CORRECTLY. FOUND OUT THAT
THE MOTOR HAS BEEN MOVED PREVIOUSLY. REMOVED SET SCREWS.
REPOSITIONED MOTOR SO IT IS FACING"UP AND DOWN" OVERRIDE LINES
UP. SECURED MOTOR TO RAM ASSMEBLY. SECURED RAM ASSEMBLY TO SLIDE
ROOM ASSEMBLY. SECURED POWER WIRES TO MOTOR. SECURED RAM TO SLIDE
ROOM ON THE OUTSIDE THROUGH THE FRAME. RAN SLIDE IN AND OUT
SEVERAL TIMES. ADJUSTED BELL AND LOCK NUTS TO MAKE SURE ROOM
PULLS IN ALL THE WAY AND PUSHES OUT ALL THE WAY. WENT DOWN TO
STORAGE SHED AND GOT A PIECE OF WOOD TO RUN ALONE THE FRAME AND
SECURE UNDERBELLY TO. CUT WOOD. PLACED WOOD ABOVE FRAME.SECURED
UNDERBELLY TO WOOD. APPLIED EXTREME TAPE TO UNDERBELLY. CLEANED
UP MESS. PARKED UNIT.

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.00	160.00	0.00

Claim : 70673

 Lab Code Job# Description LABOUR Hrs Rate Total

Z990	2	MISC LABOUR CODE (EXTERNAL)	2.30	160.00	368.00
Z990	2	MISC LABOUR CODE (EXTERNAL)	0.00	160.00	0.00
Z990	2	MISC LABOUR CODE (EXTERNAL)	0.00	160.00	0.00

Parts Total:	0.00
Labour Total:	368.00
Sublet Total:	0.00
Extras Total:	0.00

>>>> Claim Total: 368.00

Customer Signature: _____

Date: _____