



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70695



Customer #: 53657
HALL, ANDREA J.



CUSTOMER WORK ORDER

WO #: 70695

Customer: 53657 - HALL, ANDREA J. -
812-635-1011

Tag:

Author: PH

Location: 0605 CHECK PREAUTH

Stock #: 11198

Stock Desc: 2022 TT RIVERSIDE RV
INTREPID 171RDI

Chassis #: 59CCC4512NL005170

Serial #: 59CCC4512NL005170

Mileage:

Licence:

Invoice #:

Date In: 20 MAY 23

Promised:

Date Sched:

Completed: 31 MAY 23

Warr. Date: 26 MAY 23

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CORRECTION: FINAL DONE, CHECKED EVERYTHING ON SHEET, CHECKED
LP, ELECTRICAL, WATER AND APPLIANCES.

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	DGH	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DGH	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #E2 - Internal

COMPLAINT: 10K E2 EQUALIZER HITCH

CORRECTION: SET UP BRACKETS ON TONGUE.
SETUP HITCH HIGHT AND HOOKED UP TO TRAILER.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Parts

Part #	Description	Qty	Price	Total
14-1641	1000# E2 TRUNION HITCH W/BALL	1.00	N/C	N/C
44722	DELUXE STARTER KIT	1.00	N/C	N/C

Subtotal for Job #E2: 0.00

Job #BCWT - Internal

COMPLAINT: BRAKE CONTROL & WIRING - PICKUP TRUCK ONLY

CORRECTION: INSTALLED BRAKE CONTROL AND WIRING. USED A UNIVERSAL HARNESS AND
WIRED INTO THE TRUCKS TRAILER WIRING. CHECKED 7-WAY OUTPUT AND FOUND THAT THE
MARKER LIGHTS DID NOT WORK. I FOUND A BLOWN 20 AMP FUSE AND REPLACED IT. NOW THE
7-WAY WORKS AS IT SHOULD.

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------



Parts

Part #	Description	Qty	Price	Total
51140	PROPORTIONAL BRAKE CONTROL	1.00	N/C	N/C
81789	UNIVERSAL HARNESS HBCC	1.00	N/C	N/C
	UNIVERSALUNIVERSAL HARNESS			
	HBCC UNIVERSAL			

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #BCWT:

0.00

Job #DELUXE - Internal

DELUXE STARTER KIT

Subtotal for Job #DELUXE:

0.00

Job #WALK - Internal

WALK THRU

Estimated Amount: 180.00

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Subtotal for Job #WALK:

0.00

Job #1 - Warranty

 COMPLAINT: QUICK CONNECT HOSE FOR OUTSIDE SPRAYER
IS MISSING

CORRECTION: install quick connect

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	16.00

Parts

Part #	Description	Qty	Price	Total
09-7146	PF26-7003 BLUE QUICK CONNECT HOSE	1.00	32.41	32.41

Subtotal for Job #1:

48.41

Parts Total:

32.41

Labour Total:

16.00

Sublet Total:

0.00

Extras Total:

0.00

WORK ORDER TOTAL:

48.41

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 02 Jun 2023

W/O: 70695


 Customer #: 53657
HALL, ANDREA J.
