

e-Authorization

5/31/20
12:38:22

3-Authorization number PA03443943 Reference no: 70711 Status: Approved Approved by navra Approved date 5/24/2023
 Billing Name Address Address VIN Retail sold on

34 Basden's American RV Basden's American RV 4YDTGPP21NV507131 3/16/2023
 600 E Baseline Rd
 Evansville, IN 47725

Job operation of	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	6108103B Toilet - Thetford -	0.00	0.30	0.30		1	0.30	Complaint:TOILET SEAT HAS COME LOOSE. Cause:TOILET SEAT NEEDS REPLACED,BUSHING IS BROKE OUT OF IT,FILLED OUT SHEET TO ORDER. Correction:TOILET SEAT NEEDS REPLACED,BUSHING IS BROKE OUT OF IT,FILLED OUT SHEET TO ORDER.
2	3200416A Door - Interior Fol	0.00	0.50	0.20		1	0.20	Complaint:LAMINATE ON BATHROOM DOOR IS COMING LOOSE AND NEEDS TO BE GLUED BACK Cause:TOOK GLUE AND SPREAD ON DOOR PART AND USED 3 CLAMPS TO HOLD TO DRY. Correction:TOOK GLUE AND SPREAD ON DOOR PART AND USED 3 CLAMPS TO HOLD TO DRY.

3-Authorization number PA03443943
 0.50

KRV - Labor time approved in accordance with Keystone RV's flat rate manual.
 VCB: Vendor Charge Back item. (This is a Keystone RV Internal notation only)

For paper claims ~~only~~ use one pre-authorization number per warranty claim for multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the