

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 70716
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 51673 - MARY L. GENTRY
Address: 5275 E CALHOUN LN CALHOUN, IL

62419

Phone: 618-839-9248

Stock Number: 11223 - 2022 SPRINGDALE 202RD 4YDTSGJ2XN3111674

VIN: 4YDTSGJ2XN3111674 HIN: SER#: 4YDTSGJ2XN3111674

Mileage: 0

Work Order Comp: 25 MAY 23

Auth. No:

Dealer #: 1194

Warr. Date: 27 JAN 23

Work Order Date: 22 MAY 23

Inv #: 391629

WO # Job # Description JOB INFORMATION

70716 2 THE FRESH WATER TANK LEVEL INDICATOR ALWAYS SHOWS THAT THE TANK
IS EMPTY EVEN WHEN CUSTOMER KNOWS THAT TANK IS FULL OF WATER.
GOT UNDER CAMPER TO CHECK THE WIRES AT THE FRESH TANK. NOTICED
THE KIB RESISTOR PACK HAD 2 WIRES HANGING OUT. PUT PO FOR NEW
RESISTOR PACK FROM WARRANTY. TOOK PICTURES OF THE WIRES BROKEN.
WHAT MAY HAVE CAUSED THIS PROBLEM IS THE DAMAGED RESISTOR HUNG
DOWN BY THE JACKS. WHEN THE JACK WERE EXTENDED IT PULLED ON THE
RESISTOR. REMOVED DAMAGED RESISTOR AND INSTALLED NEW RESISTOR.
TIDE THE NEW RESISTOR UP OUT OF THE WAY OF THE JACKS.

Part No Job# Description PARTS Qty Price Total

10-1148 2 REPLACEMENT WIRE HARNESS 1.00 9.97 9.97

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 2 MISCELLANEOUS REPAIR 0.50 160.00 80.00

Z990 2 MISCELLANEOUS REPAIR 0.00 160.00 0.00

Parts Total: 9.97

Labour Total: 80.00

Sublet Total: 0.00

Extras Total: 0.00

>>>> Claim Total: 89.97

Customer Signature: _____

Date: _____