

e-Authorization

3-Authorization number PA03444853 Reference no: 70716 Status: Approved Approved by steic Approved date 5/24/2023
rving Name Address VIN Retail sold on

34 Basden's American RV Basden's American RV 4YDTS6J2XN3111674 1/20/2023
600 E Baseline Rd
Evansville, IN 47725

lu Root e operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	6101926A Fresh Water Tank	0.00	0.50	0.50		1	2.50	Complaint:THE FRESH WATER TANK LEVEL INDICATOR ALWAYS SHOWS THAT THE TANK IS EMPTY EVEN WHEN CUSTOMER KNOWS THAT TANK IS FULL OF WATER. Cause:GOT UNDER CAMPER TO CHECK THE WIRES AT THE FRESH TANK. NOTICED THE KIB RESISTOR PACK HAD 2 WIRES HANGING OUT. PUT PO FOR NEW RESISTOR PACK FROM WARRANTY. TOOK PICTURES OF THE WIRES BROKEN. Correction:GOT UNDER CAMPER TO CHECK THE WIRES AT THE FRESH TANK. NOTICED THE KIB RESISTOR PACK HAD 2 WIRES HANGING OUT. PUT PO FOR NEW RESISTOR PACK FROM WARRANTY. TOOK PICTURES OF THE WIRES BROKEN.

KRV - VCB

3-Authorization number PA03444853 0.50

r paper claims only use one pre-authorization number per warranty claim for
iple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
m. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the